

ASS. REC. BY:

REF: AAA / 20010657/Kb es 3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s At work
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SML 37C Yr Regn: 11, 13
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or (A)
 Make: Porsche Macan c.c. 1984
 Colour M.P. Pink A/C: Insured / Std / NI / NA
 Sp. Reading 45800 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WPI 222952GLB 05403
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: 235/60R18
 R: 255/55R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 0 mm Rear R/Bal. 0 mm
 L/Bal. 0 mm L/Bal. 0 mm
 D.O.A. 24/8/20 D.O.I. 6/10/2020
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FR O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 0120k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>29/12</u>	<u>11 hrs @ 82000 total (28/12/21)</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 1) _____
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation:	_____ \$ - RS. _____ \$
Fixes:	_____ \$
Others:	_____ \$
TOTAL	_____ \$

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
 TEL: 64528211 FAX: 64517420

ESTIMATE

Not Authorised
11 Sep @ 8200h
Painting After Paint
4 days

ONG YONG CHOK

c/o 46 Lenton Plain
 Singapore 786548

Date: 5/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: PORSCHE MACAN / SML 37 C		
1 pc	front bonnet <i>(Aluminium) 3057.90</i>	<i>Pz</i> 5,140.00 ✓
1 pc	front head lamp <i>3267.10</i>	<i>Gr</i> 3,518.40 ✓
1 pc	front head lamp lower bracket	<i>Sn</i> 316.80 X
1 pc	front bumper <i>1084.90</i>	<i>Pz</i> 2,110.00 ✓
1 pc	front bumper side retainer	<i>Sn</i> 134.10 X
1 pc	front bumper LED day light lamp	<i>Gr</i> 574.00 ✓
1 pc	front bumper fog lamp	<i>Sn</i> 672.00 X
1 pc	front bumper fog lamp garnish <i>245</i>	<i>ndl Gr</i> 479.30 ✓
1 pc	front bumper side park sensor	<i>Sen</i> 341.20 ✓
1 pc	front bumper lower pad	<i>Sn</i> 736.00 X
2 pcs	front bumper side grille fin @ 256.00	<i>ndl Dis</i> 512.00 ✓
1 pc	front bumper side grille cover	<i>Sn</i> 544.00 X
1 pc	front bumper side grille inner pad	<i>Sn</i> 416.00 X
1 pc	front wheel dust cover	<i>Sn</i> 401.00 X
20 pcs	clip assorted @ 3.40	<i>nn</i> 68.00 X
	sub total	15,962.80
	less 5% <i>10%</i>	798.14
	sub total	15,164.66
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	980.00 <i>500l</i>
	To check wiring system.	100.00 <i>30l</i>
	To apply putty & spray painting on affected areas.	850.00 <i>600l</i>
	To install front sensors.	80.00 <i>50l</i>
	To reset ECU.	<i>nn</i> 400.00 X
	total	17,574.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

ONG YONG CHOK

c/o 46 Lentor Plain

Singapore 786548

Date: 16/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: PORSCHE MACAN / SML 37 C/ SUPPLEMENTARY	
1pc	front support side panel	<i>DI</i> 494.30
1pc	front bumper side grille outer pad	<i>NI</i> 316.50
	Sub-total	810.80
	Less 5% <i>10%</i>	40.54
		770.26
	Vinyl wrap up - customised with material & installation	<i>800.00</i> 1,850.00
	Total	2,620.26