

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
 TEL: 64528211 FAX: 64517420

*Not Authorised*

*1/1 Day @  
 Recovery After Paint*

## ESTIMATE

*4 days*

**ONG YONG CHOK**  
 c/o 46 Lentor Plain  
 Singapore 786548

Date: 5/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	<b>RE: PORSCHE MACAN / SML 37 C</b>	
1 pc	front bonnet <i>(Aluminium)</i>	<i>Pr</i> 5,140.00 ✓
1 pc	front head lamp	<i>Gr</i> 3,518.40 ✓
1 pc	front head lamp lower bracket	<i>Sm</i> 316.80 X
1 pc	front bumper	<i>Pr</i> 2,110.00 ✓
1 pc	front bumper side retainer	<i>Sm</i> 134.10 X
1 pc	front bumper LED day light lamp	<i>Gr</i> 574.00 ✓
1 pc	front bumper fog lamp	672.00 ✓
1 pc	front bumper fog lamp garnish	<i>nd / Gr</i> 479.30 ✓
1 pc	front bumper side park sensor	<i>Sen</i> 341.20 ✓
1 pc	front bumper lower pad	736.00 ?
1 pc	front bumper side grille fin	<i>Pr / Dis</i> 512.00 ✓
2 pcs	front bumper side grille cover	<i>Sm</i> 544.00 X
1 pc	front bumper side grille inner pad	<i>Sm</i> 416.00 X
1 pc	front bumper side grille inner pad	<i>Sm</i> 401.00 X
1 pc	front wheel dust cover	68.00 ?
20 pcs	clip assorted	@ 3.40
	sub total	15,962.80
	less 5%	798.14
	sub total	15,164.66
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	980.00 <i>500l</i>
	To check wiring system.	100.00 <i>30l</i>
	To apply putty & spray painting on affected areas.	850.00 <i>600l</i>
	To install front sensors.	80.00 <i>50l</i>
	To reset ECU.	400.00 ?
	<b>total</b>	<b>17,574.66</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: