

ESTIMATE

ONG YONG CHOK
 c/o 46 Lentor Plain
 Singapore 786548

Date: 16/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
<u>RE: PORSCHE MACAN / SML 37 C/ SUPPLEMENTARY</u>		
1pc	front support side panel	<i>Di</i> 494.30
1pc	front bumper side grille outer pad	<i>Di</i> 316.50
Sub-total		810.80
Less 5%		40.54
<i>10%</i>		770.26
Vinyln wrap up - customised with material & installation		1,850.00 <i>800.00</i>
Total		2,620.26

Not Withheld
11 Bay @ 8200
Penalty After Paint
4 days

ESTIMATE

ONG YONG CHOK

c/o 46 Lenton Plain
 Singapore 786548

Date: 5/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)	
RE: PORSCHE MACAN / SML 37 C			
	<i>(Aluminium) 3057.90</i>		
1 pc	front bonnet	5,140.00	✓
1 pc	front head lamp	3,518.40	✓
1 pc	front head lamp lower bracket	316.80	X
1 pc	front bumper	2,110.00	✓
1 pc	front bumper side retainer	134.10	X
1 pc	front bumper LED day light lamp	574.00	✓
1 pc	front bumper fog lamp	672.00	X
1 pc	front bumper fog lamp garnish <i>245</i>	479.30	✓
1 pc	front bumper side park sensor	341.20	✓
1 pc	front bumper lower pad	736.00	X
2 pcs	front bumper side grille fin @ 256.00	512.00	✓
1 pc	front bumper side grille cover	544.00	X
1 pc	front bumper side grille inner pad	416.00	X
1 pc	front wheel dust cover	401.00	X
20 pcs	clip assorted @ 3.40	68.00	X
	sub total	15,962.80	
	less 5% <i>10%</i>	798.14	
	sub total	15,164.66	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	980.00	<i>500l</i>
	To check wiring system.	100.00	<i>30l</i>
	To apply putty & spray painting on affected areas.	850.00	<i>600l</i>
	To install front sensors.	80.00	<i>50l</i>
	To reset ECU.	400.00	X
	total	17,574.66	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: