



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103088

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 03/05/2021  
Reference CC3/CTI20010660/Kpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5375U  
Insured Veh. SLF 8364Z  
Claim No. SNM20D203668/C02  
Policy No. DMHCSNA00004132000  
Accident Date 30/09/2020  
Inspection Date 02/10/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20010660/Kpa3q2	
			Date: 03/05/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLF 8364Z	Veh. Inspected	SHD 5375U	
Policy No.	DMHCSNA00004132000	Coverage (\$)	0.00	
Claim No.	SNM20D203668/C02	Excess (\$)	0.00	
Assign From		Assign Date	02/10/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU703077042	Colour	M.P.WHITE / RED	
Odometer	191297 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	8 mm	
L/H Front Tyre	195/65 R15	SAILUN	8 mm	
R/H Rear Tyre	195/65 R15	SAILUN	8 mm	
L/H Rear Tyre	195/65 R15	SAILUN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/09/2020	Inspection Date	02/10/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5375U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER,REAR BUMPER	BUCKLED / DENTED	442.60	442.60
1	REINFORCEMENT,SUB-ASSY,REAR BUMPER	BENT	332.70	332.70
1	COVER,REAR BUMPER,LOWER	DENTED	15.40	15.40
1	GUARD,REAR BUMPER,CENTER	BENT / CRACKED	576.30	576.30
1	PANEL SUB-ASSY,BACK DOOR	TO REPAIR SEE LABOUR	1,147.80	-
1	GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	SERVICEABLE	925.60	-
1	WEATHERSTRIP,BACK DOOR	SERVICEABLE	372.30	-
1	PANEL SUB-ASSY,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
1	COVER,DECK TRIM,REAR	SERVICEABLE	126.70	-
1	SWITCH ASSY,BACK DOOR OPENER	SERVICEABLE	179.10	-
	LESS 25% DISCOUNT		-1,192.20	-341.75
			3,576.60	1,025.25
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	90.00	60.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.90	-
1	REAR TAILGATE WORDING "PRIUS" (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE WORDING "HYBRID" (SN)	NOT NECESSARY	54.60	-
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	30.00
1	REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	140.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	130.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	200.00	-
			1,907.10	790.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,BACK DOOR AND PANEL SUB-ASSY,BODY LOWER BACK.		1,200.00	200.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
			3,290.00	480.00
	<b>GRAND TOTAL</b>		<b>8,773.70</b>	<b>2,295.25</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,295.25</b>

Report Ref No. CC3/CTI20010660/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 5375U

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SHD 5375U**

**RE-INSPECTION**

