

Not Authorized  
Recovery B4 print

AAD2010-004

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5375U**

Vehicle No.: 02 OCT 2020  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**SHD 5375U**

JTDKB3FU703077042

TOYOTA

PRIUS

30.9.2020

**CHINA TAIPING**

22/11/2018

- |   | PART                                 |
|---|--------------------------------------|
| 1 | COVER, REAR BUMPER                   |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER  |
| 1 | COVER, REAR BUMPER, LOWER            |
| 1 | GUARD, REAR BUMPER, CENTER           |
| 1 | PANEL SUB-ASSY, BACK DOOR            |
| 1 | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE |
| 1 | WEATHERSTRIP, BACK DOOR              |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK      |
| 1 | COVER, DECK TRIM, REAR               |
| 1 | SWITCH ASSY, BACK DOOR OPENER        |

LIST	
\$	Bent 442.60 ✓
\$	Bent 332.70 ✓
\$	na 15.40 ✓
\$	Bent 576.30 ✓
\$	R 1,147.80 X
\$	su 925.60 X
\$	su 372.30 X
\$	R 650.30 X
\$	su 126.70 X
\$	su 179.10 X
TOTAL \$	4,768.80
25% \$	1,192.20
\$	3,576.60

**Special Nett**

- |      |                                   |
|------|-----------------------------------|
| 1SET | PARKING AID                       |
| 1SET | REAR BUMPER CLIP                  |
| 1    | REAR TAILGATE TOYOTA LOGO         |
| 1    | REAR TAILGATE WORDING 'PRIUS'     |
| 1    | REAR TAILGATE WORDING 'HYBRID'    |
| 1    | REAR TAILGATE STICKER 'TRANS-CAB' |
| 1    | REAR TAILGATE STICKER '6555-3333' |
| 1    | REAR BUMPER PROTECTOR             |
| 1    | Rear Licence Plate with Holder    |
| 2    | WINDSCREEN SEALANT                |
| 1    | WINDSCREEN INNER SPONGE SEAL      |

\$	su 700.00 ✓ Shorted
\$	na 90.00 605A
\$	na 47.90 X
\$	na 54.60 X
\$	na 54.60 X
\$	na 80.00 X
\$	na 80.00 X
\$	na 180.00 305A
\$	su 140.00 X
\$	na 150.00 X
\$	na 130.00 X

**Trans-cab Auto Services Pte Ltd**

AAD2010-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5375U

1 WINDSCREEN MOULDING	\$	<i>nn</i> 200.00	X
<b>TOTAL</b>	\$	<b>1,907.10</b>	

<b>TOTAL PARTS</b>	\$	<b>5,483.70</b>
--------------------	----	-----------------

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	1,200.00	<i>2200</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>500</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,200.00	<i>2000</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00	X

<b>TOTAL</b>	\$	<b>3,290.00</b>
--------------	----	-----------------

<b>Over All Total</b>	\$	<b>8,773.70</b>
-----------------------	----	-----------------

**(PART-BY-PART) Repair Days***15 Days**2 days*

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer Signature: Date:</p>
--