

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 09 Oct 2020

Preliminary Advice

Insured Vehicle No	: FV1599X	Accident Date	: 05/10/2020
TP Vehicle No	: SJB8512H	Assignment Date	: 05/10/2020
Make	: SUZUKI SWIFT	Est. Duration of Repair	: 3
Date of Inspection	: 07/10/2020		
Inspection At	: JOO HAK KEE AUTO PTE LTD (HQ) BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,191.45
Revised Amount	:S\$	2,256.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,256.88
 Lump Sum Repair	 :S\$	 1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is economical for repair
☐ The vehicle is not economical for repair
☐ Part-by-Part repair
☒ Lump Sum repair
- ☒ The above survey was conducted on a 'without prejudice' basis.