

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
 Toll-Free Number (1800-2255269)

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

R.O: 1495150



2020  
 1495150  
 02 OCT 2020

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 56186	Page No. : 1 of 5
Date Estimated : 02/10/2020	
Prepared By : Foong Shiuh Jye	

<b>- ESTIMATE REPAIR FOR -</b> Ng Seng Leong (Huang Shenglong) 686A Choa Chu Kang Crescent #11-240 Singapore 681686	<b>- ACCOUNT - 121</b> AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN40T	WBAXG32070DX83316	07/12/2012	528iA	0

DESCRIPTION	VALUE
To replace bumper front cover, bonnet, front left side panel, front wall and attachments. To remove and install front left door, front right side panel and attachments <i>+ LH foot inner support</i>	3,825.00 <del>2,400</del> 6,375.00 <del>1,425</del>
To spray paint bumper front cover, front left side panel, bonnet, front left door and front right side panel	4491.9 ✓ 4,991.00
To replace left headlight and reprogramming	432 ✓ 481.00
To tow accident vehicle to PML workshop.	<i>tow</i> 195.00 ✓
To replace front PDC sensor wire harness including reset and checks for proper function.	<i>plut.</i> 7,239 ✓ 266.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	✓ 150 <del>159.50</del> 177.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	✓ 150 <del>159.50</del> 177.00
Sundries	✓ 150.00
<b>Total Labour 1:</b>	<b>12,812.00</b>

DESCRIPTION	QTY	PRIC	VALUE
13 LH ENGINE HOOD HINGE	1	93.20	<i>bt</i> 7 93.20 ✓
1 FRT LH 1 SIDE PANEL BRACKET	1	35.10	<i>bt</i> 7 35.10 ✓
FRT LH FENDER	1	888.85	<i>bt</i> 888.85 ✓
BONNET	1	2,336.85	<i>bt</i> 2,336.85 ✓
Set of mount for bumper	1	33.55	<i>nn det</i> 33.55 ✓
FRT BUMPER CARRIER	1	719.50	<i>bt</i> 719.50 ✓
FRT BUMPER TOP IMPACT ABSORBER	1	60.00	<i>crs</i> 60.00 ✓
FRT BUMPER LH SPACER	1	26.25	<i>de</i> 26.25 ✓
FRT BUMPER LH FINISHER ROD	1	37.65	<i>nn</i> X 37.65 ✓



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : **b1 56186** Page No. : 2 of 5  
 Date Estimated : **02/10/2020**  
 Prepared By : **Foong Shiuh Jye**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN40T	WBAXG32070DX83316	07/12/2012	528ia	0

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TRIM PRIMED (PDC)	1	1,351.15	fn ✓ 1,351.15 ✓
FRT BUMPER BOTTOM MOUNT (M)	1	165.50	Xnn? 165.50 ✓
LH GRILLE CHROME	1	141.45	cra ? 141.45 ✓
EMBLEM GROMMET	2	0.85	nd ✓ 1.70 Xnn ✓
BMW EMBLEM 82MM	1	71.60	nd ✓ 71.60 ✓
BOWDEN CABLE FRONT	1	41.65	? 41.65 Xnn ✓
LEFT GATE	1	75.15	? 75.15 Xnn ✓
LH LOCK BONNET PASSIVE	1	189.55	bt ? 189.55 ✓
BOWDEN CABLE REAR	1	41.65	? 41.65 Xnn ✓
BONNET GAS STRUT	1	142.45	? ? 142.45 Xnn ✓
LH SUPPORT	1	30.80	? ? 30.80 Xnn ✓
CONNECTION TOP FRT	1	163.60	bt ? 163.60 ✓
CONNECTION TOP REAR	1	220.80	? 220.80 Xnn ✓
LH HEADLAMP SUPPORT	1	221.85	de ? 221.85 ✓
FRT LH COVER F REAR WHEELHOUSE	1	128.85	de ✓ 128.85 Xnn ✓
FRT LH WHEEL ARCH COVER	1	128.85	de ✓ 128.85 ✓
COVER LEFT	1	5.45	de ? 5.45 ✓
AIR DUCT	1	584.10	nec ? 584.10 ✓
LH COVER BOTTOM	1	71.30	? 71.30 Xnn ✓
SEAL BONNET REAR	1	50.75	nd ✓ 50.75 Xnn ✓
FRT LH LOCATOR SEAL	1	228.60	nec ? 228.60 ✓
SEAL ENGINE BONNET FRT	1	39.05	? 39.05 Xnn ✓
WIRING SET PDC FRONT	1	159.50	? 159.50 Xnn ✓
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	76.10	fn ✓ 76.10 ✓
LH HIGH PRESSURE NOZZLE	1	184.70	com ✓ 184.70 ✓
LAMP HOLDER FOR XENON LAMP	1	13.10	? 13.10 Xnn ✓
LH HEADLIGHT GASKET	1	34.10	nd ✓ 34.10 Xnn ✓
HEADLIGHT GASKET SET	1	34.85	nd ✓ 34.85 ✓
Guide strip with spring left	1	57.90	? 57.90 Xnn ✓
LH BI-XENON HEADLIGHT	1	2,662.90	cra ✓ 2,662.90 ✓
HEADLIGHT DRIVER MOD AHL XENON LIGH	1	840.10	cra ? 840.10 ✓
CONTROL UNIT XENON LIGHT	1	867.85	cra ? 867.85 ✓
REPAIR KIT LED MODULE	1	525.05	cra ? 525.05 ✓
REPAIR KIT HOLDER HEADLIGHT LH	1	295.65	? 295.65 Xnn ✓
LH FOG LIGHT	1	283.30	cra ? 283.30 ✓

Total Parts : **14,361.90**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date/Time 5/10/2020 11:32 Excess \$/\_\_\_\_\_

Surveyor's Name Tan Jye Sign [Signature] Labour 1 : **12,812.00**

Surveyor's Tel 92495749 Authorised Yes / No \_\_\_\_\_ Parts : **14,361.90**

Authorised Date WP Time \_\_\_\_\_ Labour 2 : **0.00**

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_ Excess : **0.00**

Surveyor's E-mail tanjye@tkb.com Total GST @ 7% : **1,902.17**

Working Days Recommend 7 & 8 days

Grand Total : **29,076.07**



**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\* 9DAYS**  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## supplementary

Estimate No. : **b1 56186**  
Date Estimated : **02/10/2020**  
Prepared By : **Foong Shiuh Jye**

**- ESTIMATE REPAIR FOR -**  
**Ng Seng Leong (Huang Shenglong)**  
**686A Choa Chu Kang Crescent**  
**#11-240**

**Singapore 681686**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLN40T</b>	<b>WBAXG32070DX83316</b>	<b>07/12/2012</b>	<b>528iA</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# Coating	480.00	0.00	480.00 <sup>nn</sup> <del>X</del>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET } <i>rec</i>		2.00		2.70
# BLIND RIVET		2.00		2.70
# HEX BOLT		5.00		7.50
# RH ENGINE HOOD HINGE <i>bt</i>		1.00		93.20
# FRT LH 2 SIDE PANEL BRACKET } <i>bt</i>		1.00		35.10
# FRT LH 3 SIDE PANEL BRACKET } <i>bt</i>		1.00		35.10
# LH LEVER		1.00		8.80
# STABILIZATION PIN } <i>bt</i>		2.00		2.10
# SUPPORT		1.00		18.15
# SUPPORT		1.00		18.15
# <del>BMW EMBLEM</del> <i>x nn</i>		<del>1.00</del>		<del>71.00</del>
# RIVET <i>rec</i>		3.00		1.50
# LH UPPER LOCK SECTION } <i>bt</i>		1.00		68.95
# RH UPPER LOCK SECTION } <i>bt</i>		1.00		68.95
# BONNET CATCH OPERATOR <i>bt</i>		1.00		41.65
# BRACKET LH <i>cr</i>		1.00		11.80
# LH AIR CHANNEL <i>de</i>		1.00		51.80
# REPAIR KIT SOCKET HOUSING 12 POL <i>dis</i>		1.00		104.15
# HORN HIGH PITCH <i>cr</i>		1.00		89.00
# INSERT DIRECTION INDICATOR LH <i>dis</i>		1.00		397.80
# BULB XENON LIGHT W/IGNITION ELEMENT <i>cr</i>		1.00		422.85
# NOTICE SAFETY CATCH <i>rec</i>		1.00		24.50
# STICK ON LABEL XENON LIGHT <i>rec</i>		1.00		24.50
#				

# SUPPLEMENTARY ITEMS

Total Labour :	480.00
Total Parts :	1,602.55
Total Labour & Parts :	2,082.55
Deduction for Excess :	

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## supplementary

Total Repair Costs less Excess:	2,082.55
GST @7%:	145.78
Grand Total :	<u>2,228.33</u>