

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

02 OCT 2020

## ESTIMATE

Estimate No. : b1 56186	Page No. : 1 of 5
Date Estimated : 02/10/2020	
Prepared By : Foong Shiuh Jye	

- ESTIMATE REPAIR FOR - Ng Seng Leong (Huang Shenglong) 685A Choa Chu Kang Crescent Singapore 681696	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN4GT	WBAXG32070DX83316	07/12/2012	528iA	0

DESCRIPTION	VALUE
To replace bumper front cover, bonnet, front left side panel, front wall and attachments. To remove and install front left door, front right side panel and attachments	3400 6,375.00
To spray paint bumper front cover, front left side panel, bonnet, front left door and front right side panel	4491.9 4,991.00
To replace left headlight and reprogramming	432 481.00
To tow accident vehicle to PML workshop.	for receipt. / 195.00
To replace front PDC sensor wire harness including reset and checks for proper function.	part. ? 239 266.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 159.50 177.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 159.50 177.00
Sundries	/ 150.00
<b>Total Labour 1: 12,812.00</b>	

DESCRIPTION	QTY	PRIC	VALUE
LH ENGINE HOOD HINGE	1	93.20	? 93.20
FRT LH 1 SIDE PANEL BRACKET	1	35.10	? 35.10
FRT LH FENDER	1	888.85	bt - 888.85
BONNET	1	2,336.85	bt - 2,336.85
Set of mount for bumper	1	33.55	de - 33.55
FRT BUMPER CARRIER	1	719.50	bt - 719.50
FRT BUMPER TOP IMPACT ABSORBER	1	60.00	cm - 60.00
FRT BUMPER LH SPACER	1	26.25	de - 26.25
FRT BUMPER LH FINISHER ROD	1	37.65	? 37.65

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 56186** Page No. : 2 of 5  
 Date Estimated : **02/10/2020**  
 Prepared By : **Foong Shiuh Jye**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN40T	WBAXG32070DX83316	07/12/2012	5281A	0

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TRIM PRIMED (PDC)	1	1,351.15	1,351.15
FRT BUMPER BOTTOM MOUNT (M)	1	165.50	165.50
LH GRILLE CHROME	1	141.45	141.45
EMBLEM GROMMET	2	0.85	1.70
BMW EMBLEM 82MM	1	71.60	71.60
BOWDEN CABLE FRONT	1	41.65	41.65
LEFT GATE	1	75.15	75.15
LH LOCK BONNET PASSIVE	1	189.55	189.55
BOWDEN CABLE REAR	1	41.65	41.65
BONNET GAS STRUT	1	142.45	142.45
LH SUPPORT	1	30.80	30.80
CONNECTION TOP FRT	1	163.60	163.60
CONNECTION TOP REAR	1	220.80	220.80
LH HEADLAMP SUPPORT	1	221.85	221.85
FRT LH COVER F REAR WHEELHOUSE	1	128.85	128.85
FRT LH WHEEL ARCH COVER	1	128.85	128.85
COVER LEFT	1	5.45	5.45
AIR DUCT	1	584.10	584.10
LH COVER BOTTOM	1	71.30	71.30
SEAL BONNET REAR	1	50.75	50.75
FRT LH LOCATOR SEAL	1	228.60	228.60
SEAL ENGINE BONNET FRT	1	39.05	39.05
WIRING SET PDC FRONT	1	159.50	159.50
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	76.10	76.10
LH HIGH PRESSURE NOZZLE	1	184.70	184.70
LAMP HOLDER FOR XENON LAMP	1	13.10	13.10
LH HEADLIGHT GASKET	1	34.10	34.10
HEADLIGHT GASKET SET	1	34.85	34.85
Guide strip with spring left	1	57.90	57.90
LH BI-XENON HEADLIGHT	1	2,662.90	2,662.90
HEADLIGHT DRIVER MOD AHL XENON LIGH	1	840.10	840.10
CONTROL UNIT XENON LIGHT	1	867.85	867.85
REPAIR KIT LED MODULE	1	525.05	525.05
REPAIR KIT HOLDER HEADLIGHT LH	1	295.65	295.65
LH FOG LIGHT	1	283.30	283.30
<b>Total Parts :</b>			<b>14,361.90</b>

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey or have the repairer resurvey  
 • To display damaged parts and resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey on a "Without Prejudice" basis  
 • No illegal modifications allowed  
 • Supplemental charges for parts covered and is subject to the relevant insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Claims OD / 3rd Party / Uninsured losses / Direct Settlement  
 Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Surveyor's Name: Tan Jye Sign: [Signature] Labour 1 : 12,812.00  
 Surveyor's Tel: 92493117 Authorised: Yes/No Parts : 14,361.90  
 Authorised Date: WP Time: \_\_\_\_\_ Labour 2 : 0.00  
 Excess : 0.00  
 RESURVEY PARTS PHOTO BY SURVEYOR Yes/No PML Yes/No Total GST @ 7% : 1,902.17  
 Surveyor's E-mail: tanjye@lkk.com Grand Total : 29,076.07  
 Working Days Recommended: 7-8 days.



**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***  
**\*\* ALL PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE \*\***