

Car-in 13/10/2020 wip: 51689

Kiam/Hong



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIR-Adam

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>torn</i>	\$	2,763.00 ✓	
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	643.00 *	
3 FRONT BUMPER CLOSING ELEMENT - CENTRE <i>? new ✓</i>	\$	220.00 ?	
4 FRONT BUMPER ADAPTER - LH / RH <i>RH only 2</i>	\$	78.00 39.	
5 FRONT BUMPER REINFORCEMENT - RH <i>new X</i>	\$	110.00 *	
6 FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$	151.00 *	
7 FRONT BUMPER CLOSING ELEMENT - LOWER <i>?</i>	\$	208.00 ?	
8 FRONT SPOILER <i>new</i>	\$	249.00 *	
9 FRONT BUMPER AIR GUIDE GRILLE - RH <i>could</i>	\$	429.00 ✓	
10 FRONT BUMPER AIR GUIDE - RH UPPER <i>could</i>	\$	28.00 ✓	
11 FRONT BUMPER AIR GUIDE - RH LOWER <i>could</i>	\$	21.00 ✓	
12 RADIATOR GRILLE <i>could</i>	\$	2,192.00 ✓	
13 RADIATOR GRILLE COVER <i>?</i>	\$	54.00 ?	
14 CONNECTOR HOUSING BRACKET - LH <i>new</i>	\$	28.00 *	
15 FRONT BUMPER CARRIER <i>new</i>	\$	960.00 *	
16 FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$	223.00 ✓	
17 FRONT BUMPER SUPPORT <i>?</i>	2 \$	59.00 ?	
18 FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$	44.00 ✓	
19 FRONT BUMPER BRACKET - RH <i>? new ✓</i>	\$	54.00 ?	
20 FRONT BUMPER COVER <i>could</i>	\$	124.00 ✓	
SUB TOTAL SPARE PARTS		\$ 8,638.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 CAUTION SIGN STICKER <i>Rec</i>	NEC	\$ 14.00	✓
22 OIL COMPLY STICKER <i>Rec</i>	NEC	\$ 20.00	+
23 FRONT PARKING AID SENSOR <i>Rec cut 12</i>		TBC	x
24 FRONT PARKING AID SEAL RING <i>Rec</i>	4	\$ 14.00	✓
25 FRONT BUMPER WIRING SET <i>Rec</i>		\$ 571.00	x.
26 HORN - RH <i>2 Rec</i>		\$ 214.00	+
27 SPRING SHACKLE - RH		\$ 47.00	✓
28 FRONT FENDER - RH <i>Distorted</i>		\$ 1,451.00	✓
29 FRONT FENDER BRACE - RH <i>2 Rec</i>		\$ 117.00	?
30 FRONT FENDER BRACKET - RH UPPER		\$ 43.00	?
31 FRONT FENDER ATTACHMENT PARTS <i>Rec</i>		\$ 42.00	x
32 WHEEL HOUSING LINER - RH <i>torn</i>		\$ 264.00	✓
33 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 70.00	?
34 WHEEL SPOILER - RH <i>Rec</i>		\$ 164.00	?
35 STONE CHIP GUARD - RH <i>Rec</i>		\$ 50.00	✓
36 FENDER TRIM LOWER BRACKET - RH		\$ 40.00	?
37 BONNET <i>Rec</i>		\$ 5,466.00	x
38 BONNET ATTACHMENT PARTS		\$ 230.00	+
39 BONNET LID HINGE - LH / RH <i>2 Rec</i>	2	\$ 340.00	+
40 BONNET IMPACT PROTECTION - LH		\$ 19.00	+
SUB TOTAL SPARE PARTS	:	\$ 9,176.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41 BONNET IMPACT PROTECTION - RH		\$ 20.00	X
42 BONNET IMPACT PROTECTION - CENTRE		\$ 44.00	X
43 BONNET STRIKER - LH / RH	2	\$ 218.00	X
44 BONNET LID LOCK	2	\$ 407.00	X
45 BONNET BOWDEN CABLE - CENTRE	2	\$ 57.00	X
46 BONNET RELEASE ELEMENT	2	\$ 57.00	X
47 BONNET RELEASE LEVER	2	\$ 13.00	X
48 HEADLIGHT MOUNTING - LH / RH	2	\$ 234.00	X
49 LED HEADLIGHT - LH / RH	2	\$ 16,864.00	8432
50 LIFT CYLINDER - LH / RH	2	\$ 392.00	?
51 LIFT CYLINDER HOSE		\$ 175.00	X
52 RADIATOR AIR GUIDE - LH / RH	2	\$ 76.00	X
53 RADIATOR AIR GUIDE - UPPER		\$ 30.00	X
54 FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 429.00	Missing
55 FRONT ALUMINIUM RIM - RH		\$ 990.00	at
56 FRONT NO PLATE	S/N	\$ 60.00	Neu
57 SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 38,180.00	
TOTAL LABOUR CHARGES	:	\$ 8,732.00	
GRAND TOTAL	:	\$ 46,912.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Front Bumper Brace RHS.

Camera Sensor wire

Front Sensor outer X (

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lj
05/10/20

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Xlt Authorised, 05 days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0727/2020/NS 13-Oct-20 Glory Tan 1 of 1 SMU 1088 B AUDI A6 DESIGN 2.0 TFSI S
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Adapter cable loom for front camera cut ✓	\$ 411.00	
TOTAL		\$ 411.00	

For Premium Automobiles Pte Ltd

Rasm

13/10/2020

 Authorised Signature

*Subject to
 approval*

