

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 CAUTION SIGN STICKER <i>NEC</i>	NEC	\$	14.00	✓
22 OIL COMPLY STICKER <i>NEC</i>	NEC	\$	20.00	✓
23 FRONT PARKING AID SENSOR <i>NEC new cut 12</i>			TBC	✓
24 FRONT PARKING AID SEAL RING <i>NEC</i>	4	\$	14.00	✓
25 FRONT BUMPER WIRING SET <i>NEC new for</i>		\$	571.00	✓
26 HORN - RH <i>NEC</i>		\$	214.00	+
27 SPRING SHACKLE - RH <i>NEC</i>		\$	47.00	✓
28 FRONT FENDER - RH <i>Distorted</i>		\$	1,451.00	✓
29 FRONT FENDER BRACE - RH <i>NEC</i>		\$	117.00	?
30 FRONT FENDER BRACKET - RH UPPER <i>?</i>		\$	43.00	?
31 FRONT FENDER ATTACHMENT PARTS <i>NEC</i>		\$	42.00	✓
32 WHEEL HOUSING LINER - RH <i>torn</i>		\$	264.00	✓
33 WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>		\$	70.00	?
34 WHEEL SPOILER - RH <i>?</i>		\$	164.00	?
35 STONE CHIP GUARD - RH <i>NEC</i>		\$	50.00	✓
36 FENDER TRIM LOWER BRACKET - RH <i>?</i>		\$	40.00	?
37 BONNET <i>NEC</i>		\$	5,466.00	✓
38 BONNET ATTACHMENT PARTS <i>?</i>		\$	230.00	+
39 BONNET LID HINGE - LH / RH <i>NEC</i>	2	\$	340.00	+
40 BONNET IMPACT PROTECTION - LH <i>NEC</i>		\$	19.00	+
SUB TOTAL SPARE PARTS	:	\$	9,176.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 1088 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41 BONNET IMPACT PROTECTION - RH	1	\$ 20.00	X
42 BONNET IMPACT PROTECTION - CENTRE	1	\$ 44.00	X
43 BONNET STRIKER - LH / RH	2	\$ 218.00	X
44 BONNET LID LOCK RH <i>He in X bro</i>	2	\$ 407.00	X
45 BONNET BOWDEN CABLE - CENTRE <i>2 Damd</i>	1	\$ 57.00	✓
46 BONNET RELEASE ELEMENT <i>can Regm all in</i>	1	\$ 57.00	X
47 BONNET RELEASE LEVER <i>new</i>	1	\$ 13.00	X
48 HEADLIGHT MOUNTING - LH / RH <i>new</i>	2	\$ 234.00	X
49 LED HEADLIGHT - LH / RH <i>RH cut</i>	2	\$ 16,864.00	8432
50 LIFT CYLINDER - LH / RH ?	2	\$ 392.00	>
51 LIFT CYLINDER HOSE <i>new</i>	1	\$ 175.00	X
52 RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 76.00	X
53 RADIATOR AIR GUIDE - UPPER <i>new</i>	1	\$ 30.00	X
54 FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	1	\$ 429.00	✓
55 FRONT ALUMINIUM RIM - RH <i>cut</i>	1	\$ 990.00	✓
56 FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓
57 SUNDRIES ?	1	\$ 300.00	>
TOTAL SPARE PARTS	:	\$ 38,180.00	
TOTAL LABOUR CHARGES	:	\$ 8,732.00	
GRAND TOTAL	:	\$ 46,912.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Front Bumper Brace RHS.

Camera Sensor wire

Front Sensor cut off X (

Infiniti - 14/10/20