



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Liong Hong Tsan Laura Reg No/Reg Date SL3000S / 23/01/201 Date In/Mileage 05/10/2020/ 0 Chassis No KNAPH81BMH5299968 Engine No D4HBGH302255 Make/Model KIA/SORENTO UM 2.2 A DIESEL 2WD ABV Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/10/2020/ 14:58	QUK	282 / Kevin Leong	22193
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 TO REPLACE REAR BUMPER & AFFECTED AREA	400				800.00
E PNT98000 PAINT WORK ON REAR BUMPER PANEL	350				350.00
E PNT88000 TO REMOVE & INSTALL REAR PARKING ASSIST					120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
M SUNDRY SUNDRIES					50.00
M COVER-RR BUMPER,UPR		1.00	696.00	20.00	556.80
M COVER-RR BUMPER LWR		1.00	650.00	20.00	520.00
M SKID PLATE-RR BUMPER		1.00	119.00	20.00	95.20
M COVER ASSY-RR BPR UNDER		1.00	88.00	20.00	70.40
M LAMP ASSY-REAR FOG,RH		1.00	129.00	20.00	103.20
M WIRING HARNESS-RR BUMPER		1.00	248.00	20.00	198.40
M RAIL ASSY-REAR BUMPER		1.00	392.00	20.00	313.60
M ANTENNA ASSY-SMARTKEY		1.00	53.00	20.00	42.40
M BRACKET ASSY-RR BUMPER SIDE,RH		1.00	25.00	20.00	20.00
M BRACKET-RR BUMPER SIDE LWR,RH		1.00	18.00	20.00	14.40
M ULTRASONIC SENSOR-S.P.A.S		1.00	215.00	20.00	172.00
M ULTRASONIC SENSOR-S.P.A.S		1.00	215.00	20.00	172.00

Estimate

SURVEYOR NAME: Taufik 97495149

SURVEYOR SIGNATURE:

DATE: 5/10/20 @ 4:30 PM

REMARKS:

Not Authorise, Repair.
Ex: to be advise. Resurvey before paint
03 days

Confirm & accepted by

Taufik @ Phant.com.

Authorized signatory and company stamp

7% GST on	Nett	3,748.40
		262.39

Total Payable 4,010.79

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.