

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 07 Oct 2020

Preliminary Advice

Vehicle No	: SBB9955B	Accident Date	: 21/09/2019
Make	: LEXUS GS250	Policy No.	: DMPCSN30757719000
Assignment Date	: 05/10/2020	Excess	: S\$500.00
Date of Inspection	: 06/10/2020	Est. Duration of Repair	: 8 days
Inspection At	: Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,810.00
Revised Amount	:S\$	9,308.00
Check Items (Estimated)	:S\$	26,362.00
Total	:S\$	35,670.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	52,816.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,184.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are still pending repair cost from repairer.