



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2008001  
INV Date 27/11/2020  
Reference CC3/CTI20010678/Ees3q2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 7774T  
Insured Veh. GW 5387Y  
Claim No. SNM20D203714  
Policy No. DMCVSNA00048312000  
Accident Date 02/10/2020  
Inspection Date 05/10/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20010678/Ees3q2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-11-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 5387Y	Veh. Inspected	SHC 7774T
Policy No.	DMCVSNA00048312000	Coverage (\$)	0.00
Claim No.	SNM20D203714	Excess (\$)	0.00
Assign From		Assign Date	05/10/2020

### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU180976	Colour	YELLOW
Odometer	115509	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/10/2020	Inspection Date	05/10/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7774T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
	LESS 20% DISCOUNT		-186.53	-90.25
			746.12	361.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	180.00	180.00
			230.00	180.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER.		350.00	320.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			720.00	550.00
<b>GRAND TOTAL</b>			<b>1,696.12</b>	<b>1,091.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,091.00</b>

Report Ref No. CC3/CTI20010678/Ees3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7774T

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 7774T

RE-INSPECTION

