

ITYCAB PTE LTD  
REPAIR ESTIMATE

Vehicle No. : SHC7774T 02/10/20  
Make : HYUNDAI  
Model : IONIQ(G3)

Steve (LKK) WA April 5/19/19, 11.09am  
2 chg  
P/P  
Ry Bel SM

Date: 02.10.20  
Insurance: CHINA  
MVA: LKE

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER X R			\$459.40 X
10	REAR BUMPER CLIPS X NM			\$22.00 X
1	REAR BUMPER CENTRE MOULDING ASSY / cut			\$451.25 /
SUB TOTAL				\$932.65
LESS 25% 20				\$186.53
DISCOUNTED TOTAL				\$746.12
1	REAR BUMPER RUBBER MAT X ARE NM			\$50.00 X
1	REAR BUMPER REVERSE SENSOR / Shafed			\$180.00 /
				\$230.00
Labour Charge				\$350.00 329
PANEL BEATING				\$250.00 200
SPRAY PAINTING CHARGE				\$120.00 37
REMOVE/REFIX REVERSE SENSOR				
TOTAL LABOUR				\$720.00
ESTIMATE TOTAL				\$1,696.12

LKK Auto Consultants hence notify the Repairer of the following:  
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: