

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 03/10/20

3P INSURANCE: NTUC

MODEL: HYUNDAI IONIQ

SURVEYOR: LKK

VEH NO.: SHC3361C

MVA: LOKE WY

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper / LR	1		\$459.40 367.52
	Rear Bumper Cover Clips / MC	10		\$22.00 25.52 17.60
	Rear Bumper Reinforcement Bracket LH X NM	1		\$138.10
	Rear Bumper Side Bracket LH / BR	1		\$55.80 44.64
	Rear Bumper Towing Cover X NM	1		\$98.80
	Rear Bumper Reflector Lamp LH / CUT	1		\$31.90 25.52
	Rear Bumper Centre Moulding Assy / CUT	1		\$451.25 361.00
	Rear Bumper Lower Centre Moulding Assy X NM	1		\$155.00
SPARE PARTS SUB TOTAL				\$1,412.25
LESS 20%				\$282.45
DISCOUNTED SPARE PARTS TOTAL				\$1,129.80
	Reverse Sensor X NM	1		\$180.00 Nett
DISCOUNTED SPARE PARTS & NETT TOTAL				\$180.00
	Panel Beating			\$450.00 320
	Spray Painting			\$300.00 200
	Remove / Replace Reverse Sensor			\$120.00 30
	Tuff Kote			\$90.00 X
	Check Lighting			\$60.00 30
LABOUR TOTAL				\$1,020.00
ESTIMATE TOTAL				\$2,329.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) W/L P/P
5/10/20, 9.15 am
2 days
P/P
Ry Del Spry