

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305426426

Date : 08/10/20

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : STEVE CHEN

Vehicle Reg No. : SHB4271C

Date of Accident : 03-Oct-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBJ8149B

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

\$1,900.00

**Final Lumpsum Repair cost**

**\$1,900.00**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : STEVE CHEN

Date : 08/10/20

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

# COMFORT DELGRO ENGINEERING

VEHICLE : SHB4271C TYPE OF CLAIM : TP  
MODEL : HYUNDAI IONIQ SURVEY BY LKK-STEVE CHEN  
JOB NO : 305426426 DATE 05/10/20

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	REAR BUMPER BEAM	1	294.80 ✓	BR
2	REAR SMART KEY ANTENNA	1	40.50 ✓	BR
	* Last Entry *			

335.30  
-20%  
268.24