

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX9288H  
RODRIGUES BRIAN CHARLES  
NO 254

SINGAPORE 508059  
TEL : FAX :  
PH : 92201695  
ATTN :

Term:

## ESTIMATE BILL

Number : EB00005540  
Date : 05/10/2020  
Case No : AD00011341  
Vehicle No : SLU6561E  
Chassis : KMHJ3812VJU628238  
Year of Mfr : 2017  
Policy No :  
Model : HYUNDAI TL  
TUCSON 1.6 GLS

| Sn                                   | DESCRIPTION                              | QTY | U PRICE  | DISC | AMOUNT   |
|--------------------------------------|------------------------------------------|-----|----------|------|----------|
| 1                                    | TAILGATE WIPER MOTOR <i>17</i>           | 1.0 | 415.00   | 0    | 415.00   |
| 2                                    | TAILGATE <i>Bedok</i>                    | 1.0 | 1,028.00 | 0    | 1,028.00 |
| 3                                    | TAILGATE LAMP RH <i>one</i>              | 1.0 | 871.00   | 0    | 871.00   |
| 4                                    | TAILGATE LAMP LH <i>one</i>              | 1.0 | 871.00   | 0    | 871.00   |
| 5                                    | TAILGATE EMBLEM <i>new</i>               | 1.0 | 29.00    | 0    | 29.00    |
| 6                                    | TAILGATE LOGO - TUCSON <i>new</i>        | 1.0 | 29.00    | 0    | 29.00    |
| 7                                    | TAILGATE LOGO - TURBO S <i>new</i>       | 1.0 | 57.00    | 0    | 57.00    |
| 8                                    | TAILGATE OUTER GARNISH <i>De/10.11</i>   | 1.0 | 595.00   | 0    | 595.00   |
| 9                                    | TAILGATE TRIMBOARD <i>17 X</i>           | 1.0 | 242.00   | 0    | 242.00   |
| 10                                   | TAILGATE COVER                           | 1.0 | 595.00   | 0    | 595.00   |
| 11                                   | TAILGATE WEATHERSTRIP                    | 1.0 | 126.00   | 0    | 126.00   |
| 12                                   | TAILGATE LOCK <i>17</i>                  | 1.0 | 677.00   | 0    | 677.00   |
| 13                                   | TAILGATE ABSORBER RH <i>17</i>           | 1.0 | 1,009.00 | 0    | 1,009.00 |
| 14                                   | TAILGATE ABSORBER LH <i>17</i>           | 1.0 | 1,009.00 | 0    | 1,009.00 |
| 15                                   | REAR BUMPER <i>De/10.17</i>              | 1.0 | 446.00   | 0    | 446.00   |
| 16                                   | REAR BUMPER RETAINER RH <i>17</i>        | 1.0 | 25.00    | 0    | 25.00    |
| 17                                   | REAR BUMPER RETAINER LH <i>17</i>        | 1.0 | 25.00    | 0    | 25.00    |
| 18                                   | REAR BUMPER REINFORCEMENT                | 1.0 | 271.00   | 0    | 271.00   |
| 19                                   | REAR BUMPER BRACKET RH <i>17</i>         | 1.0 | 25.00    | 0    | 25.00    |
| 20                                   | REAR BUMPER BRACKET LH <i>17</i>         | 1.0 | 25.00    | 0    | 25.00    |
| 21                                   | REAR BUMPER CENTER GARNISH <i>one</i>    | 1.0 | 334.00   | 0    | 334.00   |
| 22                                   | REAR BUMPER GARNISH RH                   | 1.0 |          |      |          |
| 23                                   | REAR BUMPER GARNISH LH                   | 1.0 |          |      |          |
| 24                                   | REVERSE SENSOR                           | 4.0 | 140.00   | 0    | 560.00   |
| List Price - Parts Sub Total         |                                          |     |          |      | 9,264.00 |
| 25                                   | WINDSCREEN SEALANT <i>new</i>            | 2.0 | 24.00    | 0    | 48.00    |
| 26                                   | REVERSE CAMERA                           | 1.0 | 580.00   | 0    | 580.00   |
| 27                                   | END PANEL - REPAIR <i>R X</i>            | 1.0 |          |      |          |
| Special Nett Price - Parts Sub Total |                                          |     |          |      | 628.00   |
| Parts Total                          |                                          |     |          |      | 9,892.00 |
| 28                                   | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 800.00   | 0    | 800.00   |
| 29                                   | SPRAY PAINT ON THE AFFECTED AREAS        | 1.0 | 800.00   | 0    | 800.00   |
| 30                                   | ANTI-RUST COATING                        | 1.0 | 120.00   | 0    | 120.00   |

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX9288H  
RODRIGUES BRIAN CHARLES  
NO 254

SINGAPORE 508059  
TEL : FAX :  
PH : 92201695  
ATTN :

## ESTIMATE BILL

Number : EB00005540  
Date : 05/10/2020  
Case No : AD00011341  
Vehicle No : SLU6561E  
Chassis : KMHJ3812VJU628238  
Year of Mfr : 2017  
Policy No :  
Model : HYUNDAI TL  
TUCSON 1.6 GLS

### Term:

| Sn                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | DESCRIPTION                      | QTY | U_PRICE     | I GST DISC | AMOUNT   |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-----|-------------|------------|----------|
| 31                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | TO REMOVE & REFIT WINDSCREEN     | 1.0 | 180.00      | 0          | 180.00   |
| 32                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | TO REMOVE & REFIT REVERSE SENSOR | 1.0 | 150.00      | 0          | 150.00   |
| 33                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | WIRING                           | 1.0 | 80.00       | 0          | 80.00    |
| Labour 1 Sub Total                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                  |     |             |            | 2,130.00 |
| <div><p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><p>Acknowledged by Repairer<br/>Signature:<br/>Date:</p></div> |                                  |     |             |            |          |
| SINGAPORE DOLLARS : TWELVE THOUSAND EIGHT HUNDRED SIXTY-THREE AND CENTS FIFTY-FOUR ONLY                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                  |     | Less Excess | 0.00       |          |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                  |     | SUBTOTAL    | 12,022.00  |          |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                  |     | GST 7.00%   | 841.54     |          |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                  |     | TOTAL       | 12,863.54  |          |

Date of accident : 03/10/2020 10:53 AM. Place : PIE (TUAS) BEFORE TOA PAYOH EXIT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE