

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CC6/11/20010684/Uba3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 6581 E
lockwood

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 79k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lump Sum:

131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LA 54921

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU 6581 E

Yr Regn:

1217

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Hyundai TL Tucson c.c. *1591*

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

30101

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHJ3812VJU4628238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 6/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/10/20

D.O.I.

12/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep OK.

En: 1758.90

5/11/20 Confirmed P/P # 4668 with Anysee

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

14k Jasper

TO : SXXX9288H
RODRIGUES BRIAN CHARLES
NO 254

SINGAPORE 508059
TEL : FAX :
PH : 92201695
ATTN :

not authorized
20%
46681
Take photo before parting.
including parts.
of days.

ESTIMATE BILL

Number : EB00005540
Date : 05/10/2020
Case No : AD00011341
Vehicle No : SLU6561E
Chassis : KMHJ3812VJU628238
Year of Mfr : 2017
Policy No :
Model : HYUNDAI TL
TUCSON 1.6 GLS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE WIPER MOTOR <i>11</i>	1.0	415.00	0	415.00
2	TAILGATE <i>Bedok</i>	1.0	1,028.00	0	1,028.00
3	TAILGATE LAMP RH <i>one 825</i>	1.0	871.00	0	871.00
4	TAILGATE LAMP LH <i>one 825</i>	1.0	871.00	0	871.00
5	TAILGATE EMBLEM <i>new</i>	1.0	29.00	0	29.00
6	TAILGATE LOGO - TUCSON <i>new</i>	1.0	29.00	0	29.00
7	TAILGATE LOGO - TURBO S <i>new</i>	1.0	57.00	0	57.00
8	TAILGATE OUTER GARNISH <i>De/10.11</i>	1.0	595.00	0	595.00
9	TAILGATE TRIMBOARD <i>11 X</i>	1.0	242.00	0	242.00
10	TAILGATE COVER <i>11</i>	1.0	595.00	0	595.00
11	TAILGATE WEATHERSTRIP <i>11</i>	1.0	126.00	0	126.00
12	TAILGATE LOCK <i>11</i>	1.0	677.00	0	677.00
13	TAILGATE ABSORBER RH <i>11</i>	1.0	1,009.00	0	1,009.00
14	TAILGATE ABSORBER LH <i>11</i>	1.0	1,009.00	0	1,009.00
15	REAR BUMPER <i>De/cur</i>	1.0	446.00	0	446.00
16	REAR BUMPER RETAINER RH <i>11</i>	1.0	25.00	0	25.00
17	REAR BUMPER RETAINER LH <i>11</i>	1.0	25.00	0	25.00
18	REAR BUMPER REINFORCEMENT NN	1.0	271.00	0	271.00
19	REAR BUMPER BRACKET RH <i>11</i>	1.0	25.00	0	25.00
20	REAR BUMPER BRACKET LH <i>11</i>	1.0	25.00	0	25.00
21	REAR BUMPER CENTER GARNISH <i>cur</i>	1.0	334.00	0	334.00
22	REAR BUMPER GARNISH RH <i>11</i>	1.0			
23	REAR BUMPER GARNISH LH <i>11</i>	1.0			
24	REVERSE SENSOR <i>SW</i>	4.0	140.00	0	560.00
List Price - Parts Sub Total					9,264.00
25	WINFSCREEN SEALANT <i>new S. Net 4.</i>	2.0	24.00	0	48.00
26	REVERSE CAMERA <i>SW</i>	1.0	580.00	0	580.00
27	END PANEL - REPAIR <i>R X</i>	1.0			
Special Nett Price - Parts Sub Total					628.00
Parts Total					9,892.00
28	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
29	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
30	ANTI-RUST COATING	1.0	120.00	0	120.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Page 1 of 2

* N = Item not subjected to GST

P- 4235
20%
P- 3388

S. Net - 60
L - 1220

Issued by : Anysia

4668

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX9288H
RODRIGUES BRIAN CHARLES
NO 254

SINGAPORE 508059
TEL : FAX :
PH : 92201695
ATTN :

ESTIMATE BILL

Number : EB00005540
Date : 05/10/2020
Case No : AD00011341
Vehicle No : SLU6561E
Chassis: KMHJ3812VJU628238
Year of Mfr 2017
Policy No
Model : HYUNDAI TL
TUCSON 1.6 GLS

Term:

Sn	DESCRIPTION	QTY	U PRICE	1-GST DISC	AMOUNT
31	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
32	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
33	WIRING	1.0	80.00	0	80.00
Labour 1 Sub Total					2,130.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : TWELVE THOUSAND EIGHT HUNDRED SIXTY-THREE AND CENTS FIFTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		12,022.00
			GST 7.00%		841.54
			TOTAL		12,863.54

Date of accident : 03/10/2020 10:53 AM. Place : PIE (TUAS) BEFORE TOA PAYOH EXIT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX9288H
RODRIGUES BRIAN CHARLES
NO 25A TOH AVENUE

SINGAPORE 508059
TEL : FAX :
PH : 92201695
ATTN :

ESTIMATE BILL

Number : EB00005562
Date : 03/11/2020
Case No : AD00011341
Vehicle No : SLU6561E
Chassis : KMHJ3812VJU628238
Year of Mfr : 2017
Policy No :
Model : HYUNDAI TL
TUCSON 1.6 GLS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE UPPER GARNISH MOULDING	1.0	CNE 67.00	20%	67.00
	List Price - Parts Sub Total				67.00
2	REAR NUMBER PLATE HOLDER	1.0	SEN 30.00	0	30.00
	Special Nett Price - Parts Sub Total				30.00
	Parts Total				97.00
SINGAPORE DOLLARS : ONE HUNDRED THREE AND CENTS SEVENTY-NINE ONLY			Less Excess		0.00
			SUBTOTAL		97.00
			GST 7.00%		6.79
			TOTAL		103.79

Date of accident : 03/10/2020 10:53 AM. Place : PIE (TUAS) BEFORE TOA PAYOH EXIT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE