

LEANG AUTOMOTIVE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TO	: INDIA INTERNATIONAL	DATE	: 7/10/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: smj6554Y		Tealia.
VEHICLE MODEL	: HONDA SHUTTLE HYBRID		
CHASSIS NO	: GP72003043		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	LEANG / 90286516	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Rebond</i>	1	\$ 1,350.60	\$ 1,350.60 1150
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 26.50	\$ 53.00
3	REAR BUMPER SIDE COVER <i>new</i>	2	\$ 45.00	\$ 90.00
4	REAR BUMPER SIDE COVER REFLECTOR <i>new</i>	2	\$ 48.00	\$ 96.00
5	REAR BUMPER SIDE SPONGE <i>new</i>	2	\$ 89.50	\$ 179.00
6	REAR END PANEL <i>Repair</i>	1	\$ 560.80	\$ 560.80
7	REAR END PANEL TOP GARNISH <i>3 x new</i>	1	\$ 155.50	\$ 155.50
8	REAR END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 85.00	\$ 85.00
9	TAILGATE <i>Dented</i>	1	\$ 1,193.00	\$ 1,193.00
10	TAILGATE LOCK <i>new</i>	1	\$ 187.50	\$ 187.50
11	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 168.50	\$ 168.50
12	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 320.00	\$ 320.00
13	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 125.00	\$ 125.00
14	HONDA LOGO <i>new</i>	1	\$ 38.50	\$ 38.50
15	SHUTTLE EMBLEM <i>new</i>	1	\$ 55.00	\$ 55.00
16	HYBRID EMBLEM <i>new</i>	1	\$ 75.00	\$ 75.00

TOTAL PRICE: \$ 4,732.40
LESS 20% \$ 946.48
SUB TOTAL PRICE: \$ 3,785.92

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 30.
2	REVERSE SENSOR <i>Dented</i>	1 SET	\$ 280.00	\$ 280.00 20.

3	REAR END PANEL SEALANT <i>3 ALP</i>	1 SET	\$ 60.00	\$ 60.00	*
4	TAILGATE INNER TRIM BOARD CLIPS <i>3 ALP</i>	1 SET	\$ 50.00	\$ 50.00	*
5	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 100.00	\$ 100.00	60.
			TOTAL :	\$ 540.00	

290

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	500	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	\$ 150.00	60	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
8	TO REMOVE AND REFIT TAILGATE GLASS	\$ 180.00	120	
		TOTAL:	\$ 3,180.00	

1300

ESTIMATE REPORT

TOTAL PARTS COST: \$ 4,325.92

TOTAL LABOUR COST: \$ 3,180.00

TOTAL REPAIR COST: \$ 7,505.92

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 3741.60
L/S: 3K11 ✓
04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: