

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20010706/R1VF3E2

**Date:** 02/11/2020

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00123552000
<b>Claimant Vehicle No :</b>	SGR8898X	<b>Insured Vehicle No :</b>	SJF2U
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203689/C02/THAMYL

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGR8898X</b>		
Make & Model:	LAND ROVER RANGE ROVER SPORT, 3.0 D HSE TDV6 (L320) (A)	Engine No:	1294598306DT
Reg. Date:	22/07/2020 (Man. Year: 2019)	Chassis No:	SALWA2AK3KA850777
Colour:	Grey	Odometer:	4616 km
Engine Capacity:	2993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	275/45 R21	Rear Tyre Size:	275/45 R21
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,205.00	2,200.00	3,005.00	57.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,205.00</b>	<b>2,200.00</b>	<b>3,005.00</b>	<b>57.73</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>364.35</b>	<b>154.00</b>	<b>210.35</b>	<b>57.73</b>
<b>Nett Amount (S\$)</b>	<b>5,569.35</b>	<b>2,354.00</b>	<b>3,215.35</b>	<b>57.73</b>

#### INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	07/10/2020	Inspected At:
		Wearnes Automotive Pte Ltd (HQ) 45 LENG KEE ROAD Singapore 159103
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 Oct 2020)

**Parts:**            M1-SUV      LAND ROVER RANGE ROVER SPORT 3.0 D HSE TDV6 (L320) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGR8898X)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT & REPAIR REAR RH DOOR	New	2,400.00	1,200.00
2	TO SPRAYPAINT ON REAR LH DOOR, FENDER REAR LH, REAR LH RIM	New	2,000.00	1,000.00
3	WHEEL ALIGNMENT	New	280.00	0.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >