

ASSIGNMENT

COE 2027 NOV

From: _____ Date: _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 30001551758Claims No. 248881


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: P/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHIA 2172-2 Yr Regn: Nov / 2019Type: M.Car / M.Cycle / Bus / Van / Lorry / 7axl Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 99428 T/Radio: Insured / Std / NI / NAEng/No: G4LEK U401745C/No: KMHG851CVLU187924Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 / 65 R15R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Duratur

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 04/10/2020 D.O.A. 06/10/2020Survey held at Biprost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body y O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSG 8MS8170H
07/11/20	@ 4.43pm refused to Chua Nyuk Pui wa Merimen.
28/12/2020	From P/P 11,456.52 with 6 days of my ceda 513910.67, 55%

Date/Time, File Pass to?



Prel. Report

1) 29/12/2020



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: MEK-TPLump Sum / I.B.R. (\$) 11456.52

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 5-Oct-20

INSURANCE: MSIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 2172 Z

Description	Qty	List Price	Amount
Frt Door(RH) <i>St</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>Rec</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (RH) <i>HW</i>	1	\$ 750.40	\$ 750.40
Front Door Outer Handle (RH) <i>Rec</i>	1	\$ 234.80	\$ 234.80
Front Door Trim Board (RH) <i>HW</i>	1	\$ 796.80	\$ 796.80
Front Door Outer Moulding (RH) <i>Cut destroyed</i>	1	\$ 110.10	\$ 110.10
Rear Door (RH) <i>St</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Door Rubber(RH) <i>Rec</i>	1	\$ 270.00	\$ 270.00
Rear Door Outer Moulding(RH) <i>Cut destroyed</i>	1	\$ 125.30	\$ 125.30
Rear Door Gear/Regulator(RH) <i>HW</i>	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (RH) <i>HW</i>	1	\$ 256.80	\$ 256.80
Rear Door Hinge Upper (RH) <i>HW</i>	1	\$ 173.88	\$ 173.88
Rear Door Hinge Lower (RH) <i>HW</i>	1	\$ 170.50	\$ 170.50
Rear Door Check(RH) <i>HW</i>	1	\$ 85.92	\$ 85.92
Rear Door Trim Board (RH) <i>HW</i>	1	\$ 613.60	\$ 613.60
Rear Door Protector(RH) <i>HW</i>	1	\$ 166.20	\$ 166.20
Door Centre Pillar Outer (RH) <i>HW</i>	1	\$ 3,764.90	\$ 3,764.90
Rocker Panel Outer Garnish <i>Cut</i>	1	\$ 715.60	\$ 715.60
Rocker Panel Outer <i>HW</i>	1	\$ 1,799.60	\$ 1,799.60
Rear Bumper <i>Cut</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Cover Clips <i>Rec</i>	1	\$ 22.00	\$ 22.00
Rear Fender(RH) <i>Destroyed</i>	1	\$ 1,768.30	\$ 1,768.30
Assy BSD Blind Spot Radar (RH) <i>HW</i>	1	\$ 1,625.00	\$ 1,625.00
Rear Tyre Rim (RH) <i>HW destroyed</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (RH) <i>Cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>2 Dam</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(RH) <i>2 destroyed</i>	1	\$ 265.40	\$ 265.40
Rear Assist (RH) <i>2 destroyed</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(RH) <i>2 destroyed</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (RH) <i>HW</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (RH) <i>HW</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (RH) <i>HW</i>	1	\$ 175.60	\$ 175.60
Rear Crossmember <i>HW</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>HW</i> 11226-90	1	\$ 387.30	\$ 387.30
Stabilizer Link (RH) <i>HW</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(RH) <i>2 destroyed</i> 8981-52	1	\$ 239.50	\$ 239.50
Rear Lower Arm(RH) <i>2 destroyed</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (RH) <i>2 destroyed</i>	1	\$ 538.10	\$ 538.10
SUB TOTAL			\$ 24,482.74
LESS 20%			\$ 4,896.55
DISCOUNTED TOTAL			\$ 19,586.19

Rear Door Comfortdelgro & Apps Sticker(RH) <i>Nuc</i>	SN	1	\$ 80.00	\$ 80.00	✓
Rear Tyre(RH) <i>HW</i>	SN	1	\$ 216.00	\$ 216.00	X
Front Door Comfort Logo (RH) <i>Nuc</i>	SN	1	\$ 75.00	\$ 75.00	✓
<i>155-00</i> SUB TOTAL				\$ 371.00	
Labour Charge					
Panel Beating		1	\$1,600.00	\$1,600.00	900/-
Spray Painting Charge		1	\$1,400.00	\$1,400.00	900/-
Wiring Charge		1	\$140.00	\$140.00	HW
Tuff Kote		1	\$160.00	\$160.00	40/-
Towing Charge		1	\$80.00	\$80.00	HW
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	150/-
Re-set Rear ABS System		1	\$400.00	\$400.00	HW
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System		1	\$200.00	\$200.00	HW
Transfer of Door Mechanism REAR		1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System <i>2320-00</i>		1	\$200.00	\$200.00	HW
Four Wheel Alignment		1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/-
TOTAL LABOUR				\$5,410.00	
ESTIMATE TOTAL				\$ 25,367.19	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

06/10/22 c 1700hr

HA Andrew

Part by Part.

Man 6 days

LKK Auto

8

Photo of the car
with damaged
parts.

P/P 11456.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: