

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJT 502U
TP/MSIG

MS : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

TTN: Motor Claim Department

Estimate No: ES2090834/YISHUN

Date: 19 Oct 2020

Policy No: 5118972549

Veh Reg No: SJT502U

Make/Model: TOYOTA VIOS J GRADE
MANUAL
(INSTRUCTOR BRAKE)

Chassis No: MHFBT9F3206070039

Engine No: 1NZZ292080

Reg. Date: 10/03/2016

S Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 03/10/2020

Veh Reg No: SGH6555B

Not Notarised
Returning By Claim
3 days

Estimate Repair Cost to Vehicle No :SJT502U

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT BUMPER	429.00	1 PC	429.00	—
2 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	—
			450.00	
		Less 25%	112.50	337.50
Labour				
REMOVE & REFIX FRT BUMPER ASSY,GRILLE,FOG LAMP & GARNISH,LOWER GRILLE,KNOCK & REPAIR FRT RH FENDER & REALIGN THE SAME	300.00	1 LA	300.00	200
PUTTY & RESPRAY ON FRT RH FENDER,FRT BUMPER	450.00	1 LA	450.00	400
			750.00	750.00
			Total	SS 1,087.50
			Add GST @ 7%	76.13
			Total Amount Payable	SS 1,163.63

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: