



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100853

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 08/02/2021
Reference CC4/FCI20010714/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLQ 5218A
Insured Veh. SHD 4728S
Claim No. D20004014MFSH
Policy No. D-20094922MFSH
Accident Date 30/09/2020
Inspection Date 07/10/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010714/R1ra3q2	
			Date: 08/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4728S	Veh. Inspected	SLQ 5218A	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004014MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	06/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS RX200T LUX	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTJBAMCA402034218	Colour	BLACK	
Odometer	47672 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm	
L/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/09/2020	Inspection Date	07/10/2020	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5218A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COVER ,RR BUMPER (SN)	DEFORMED	1,030.60	1,030.60
1	EXTENSION ,SUB-ASSY (SN)	DEFORMED	570.40	570.40
1	RETAINER ,RR BUMPER (SN)	SERVICEABLE	161.10	-
1	EXTENSION ,SUB-ASSY (SN)	SERVICEABLE	307.20	-
1	PLATE ,RR BUMPER (SN)	SERVICEABLE	43.50	-
1	PLATE ,BUMPER (SN)	NECESSARY	24.50	24.50
1	BRACKET ,RR BUMPER (SN)	NECESSARY	24.50	24.50
10	CLIP (SN)	NECESSARY	25.00	25.00
1	RETAINER ,RR BUMPER (SN)	SERVICEABLE	200.60	-
1	ABSORBER ,RR BUMPER (SN)	CRACKED	112.40	112.40
1	REINFORCEMENT ,RR (SN)	SERVICEABLE	536.10	-
1	RETAINER ,RR BUMPER (SN)	SERVICEABLE	149.90	-
1	RETAINER ,OUTSIDE (SN)	NECESSARY	3.90	3.90
2	TAPE ,SEAL (SN)	NECESSARY	9.60	9.60
2	SCREW ,W/WASHER (SN)	NECESSARY	3.80	3.80
2	RETAINER ,ULTRASONIC (SN)	NECESSARY	83.20	83.20
2	RETAINER ,ULTRASONIC (SN)	NECESSARY	38.40	38.40
2	SENSOR ,ULTRASONIC (SN)	SERVICEABLE	981.60	-
4	CLIP ,ULTRASONIC (SN)	NECESSARY	49.20	49.20
1	REFLECTOR ,ASSY (SN)	SERVICEABLE	48.80	-
			4,504.30	2,025.50
<u>LABOUR</u>				
TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIR AND STRAIGHTEN ON REAR BUMPER ,REAR PANEL AND FIX NEW PARTS.			1,732.00	866.00
TO SPRAY PAINT ON REAR BUMPER .			1,484.00	742.00
TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER .			216.50	216.50
TO RESET ECU AND REPROGRAMME.			216.50	216.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST.		216.50	216.50
			3,865.50	2,257.50
GRAND TOTAL			8,369.80	4,283.00
RECOMMENDED COST OF REPAIRS				4,283.00

Report Ref No. CC4/FCI20010714/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 5218A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 5218A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

