

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1725C

HO KIM FOK

NO

SINGAPORE

TEL : FAX :

PH : 96349336

ATTN :

Term:

ESTIMATE BILL

Number : EB00004804

Date : 20/4/2018

Case No : AD00009685

Vehicle No : SLS8312E

Chassis: WDD2211572A407947

Year of Mfr 2011

Policy No 5095549424

Model : MERCEDES BENZ S
350 CGI L

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT LAMP COVER LH ?	1.0	340.00	0	340.00
2	FRONT DOOR SIDE MIRROR LH ✓	1.0	1,365.00	0	1,365.00
3	FRONT RIM HUB BEARING LH ?	1.0	680.00	0	680.00
4	FRONT LOWER ARM LH ?	1.0	780.00	0	780.00
5	FRONT SHOCK ABSORBER LH ?	1.0	3,200.00	0	3,200.00
Nett Price - Parts Sub Total					6,365.00
6	FRONT RIM LH ✓	1.0	1,300.00	0	1,300.00
7	FRONT TYRE LH ?	1.0	680.00	0	680.00
8	FRONT FENDER LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					1,980.00
Parts Total					8,345.00
9	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
10	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
11	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
12	WIRING	1.0	40.00	0	40.00
13	TWO WHEEL ALIGNMENT	1.0	25.00	0	25.00
Labour 1 Sub Total					1,415.00
SINGAPORE DOLLARS : TEN THOUSAND FOUR HUNDRED FORTY-THREE AND CENTS TWENTY ONLY			Less Excess		0.00
			SUBTOTAL		9,760.00
			GST 7.00%		683.20
			TOTAL		10,443.20

200
300
X NN
✓
✓

Date of accident : 19/04/2018 02:40 PM. Place : UPPER SERANGOON ROAD > CITY

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

REPAIR COST WILL BE REVIEW WHEN ADDITIONAL PHOTOS PROVIDED 3230 3 days

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE