

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1725C

HO KIM FOK
NO

SINGAPORE
TEL : FAX :
PH : 96349336
ATTN :

ESTIMATE BILL

Number : EB00004804
Date : 20/4/2018
Case No : AD00009685
Vehicle No : SLS8312E
Chassis : WDD2211572A407947
Year of Mfr : 2011
Policy No : 5095549424
Model : MERCEDES BENZ S
350 CGI L

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT	
1	FRONT LAMP COVER LH X SVC	1.0	340.00	0	340.00	
2	FRONT DOOR SIDE MIRROR LH ✓	1.0	1,365.00	0	1,365.00	
3	FRONT RIM HUB BEARING LH X SVC	1.0	680.00	0	680.00	
4	FRONT LOWER ARM LH X SVC	1.0	780.00	0	780.00	
5	FRONT SHOCK ABSORBER LH X SVC	1.0	3,200.00	0	3,200.00	
	Nett Price - Parts Sub Total				6,365.00	
6	FRONT RIM LH ✓	1.0	1,300.00	0	1,300.00	
7	FRONT TYRE LH X SVC	1.0	680.00	0	680.00	
8	FRONT FENDER LH - REPAIR	1.0				
	Special Nett Price - Parts Sub Total				1,980.00	
	Parts Total				8,345.00	
9	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00	200
10	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00	300
11	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00	X NN
12	WIRING	1.0	40.00	0	40.00	✓
13	TWO WHEEL ALIGNMENT	1.0	25.00	0	25.00	✓
	Labour 1 Sub Total				1,415.00	
SINGAPORE DOLLARS : TEN THOUSAND FOUR HUNDRED FORTY-THREE AND CENTS TWENTY ONLY			Less Excess		0.00	
			SUBTOTAL		9,760.00	
			GST 7.00%		683.20	
			TOTAL		10,443.20	

Date of accident : 19/04/2018 02:40 PM. Place : UPPER SERANGOON ROAD > CITY

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

REPAIR COST WILL BE REVIEW WHEN ADDITIONAL PHOTOS PROVIDED 3230 3 days

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE