



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

INV No. AC2100642

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 01/02/2021
Reference CC6/QBE20010717/Ura3q2
Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. AV 7297L
Insured Veh. SMA 5868X
Claim No. VC014009
Policy No. 8-V0018361-MVA-R001
Accident Date 28/09/2020
Inspection Date 06/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC6/QBE20010717/Ura3q2	
			Date: 01/02/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 5868X	Veh. Inspected	AV 7297L
	Policy No.	8-V0018361-MVA-R001	Coverage (\$)	0.00
	Claim No.	VC014009	Excess (\$)	0.00
	Assign From		Assign Date	06/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA NC750X	c.c	745
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JH2RC72AXEK001303	Colour	GREY
	Odometer	98387 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70Z R17	BRIDGESTONE	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60Z R17	BRIDGESTONE	7 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/09/2020	Inspection Date	06/10/2020
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AV 7297L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SIGNAL LAMP O/S	SCRATCHED	152.00	130.00
1	REAR EXHAUST	SERVICEABLE	920.00	-
1	FRONT FOOTREST N/S	BROKEN	180.00	85.00
1	FRONT FOOTREST BRACKET N/S	BENT	250.00	166.00
1	GEAR LEVER	CUT	145.00	145.00
1	SIDE STAND HOLDER	CUT	85.00	85.00
1	SIDE STAND	TO REPAIR SEE LABOUR	285.00	-
1	FRONT MIRROR N/S	CUT	145.00	145.00
1	FRONT HAND GUARD N/S	CUT	285.00	285.00
1	FRONT CLUTCH LEVER	SCRATCHED	145.00	115.00
1	FRONT BALANCER N/S	SCRATCHED	60.00	60.00
1	HANDLE BAR	BENT	645.00	480.00
1	FRONT FORK ASSY N/S	TO REPAIR SEE LABOUR	1,050.00	-
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	980.00	-
1	HORN UNIT	CRACKED	285.00	285.00
1	FRONT SIGNAL LAMP N/S	SCRATCHED	150.00	130.00
1	FRONT SIDE TOP GARNISH N/S	CRACKED	380.00	380.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	350.00	-
1	FRONT FAIRING	TO REPAIR SEE LABOUR	1,050.00	-
	LESS 10% DISCOUNT		-	-249.10
			7,542.00	2,241.90
	<u>SPECIAL NETT ITEMS</u>			
1	REAR GIVI SIDE BOX O/S (SN)	BROKEN	980.00	450.00
1	REAR GIVI SIDE BOX BRACKET O/S (SN)	BENT	450.00	300.00
1	REAR GIVI SIDE BOX N/S (SN)	CUT	980.00	450.00
1	REAR GIVI TOP BOX (SN)	CUT	980.00	800.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	12.00

Report Ref No. CC6/QBE20010717/Ura3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SAFF GUARD BRACKET TOP N/S (SN)	CUT	800.00	500.00
1	FRONT SAFF GUARD BRACKET BOTTOM N/S (SN)	CUT	600.00	300.00
			4,810.00	2,812.00
	<u>LABOUR</u>			
	TO REALIGN FRONT FORK .		80.00	60.00
	TO SPRAY PAINTING .		500.00	220.00
	LABOUR FOR REPLACED PARTS.INCLUSIVE OF THE REPAIR OF SIDE STAND ,FRONT FORK ASSY N/S,FRONT SPORT RIM,FRONT FENDER AND FRONT FAIRING .		500.00	300.00
			1,080.00	580.00
GRAND TOTAL			13,432.00	5,633.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00
---	--	--	-----------------

Report Ref No. CC6/QBE20010717/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. AV 7297L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. AV 7297L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. AV 7297L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

