

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Boo Yong Kwang
Blk 258 Serangoon Central Drive
#13-06
Singapore 550258

SMR
Vehicle No : ~~SML~~ 7523 M
Make : Toyota Noah
Year : 2019

Not Authorized

Returning B4 pain

L1 Smp @ 5600 6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front o/s rocker panel garnish	<i>Sm</i>	\$755.20	X
1 pc	Rear o/s sliding door assy	<i>B1</i>	\$2,025.10	✓
1 pc	Rear o/s sliding door glass frame black sticker	<i>mm</i>	\$155.70	✓
1 pc	Rear o/s sliding door glass outer moulding	<i>Bu</i>	\$206.10	✓
1 pc	Rear o/s sliding door inner lock <i>502-60</i>	<i>Bd</i>	\$550.70	✓
1 pc	Rear o/s sliding door sensor	<i>Od</i>	\$485.90	✓
1 pc	Rear o/s sliding door roller	<i>Sm</i>	\$285.70	X
1 pc	Rear o/s sliding door roller bracket	<i>R</i>	\$263.10	✓
1 pc	Rear o/s sliding door inner trim board	<i>mg cm</i>	\$628.70	✓
1 pc	Rear o/s sliding door power window motor	<i>Im</i>	\$496.10	✓
1 pc	Rear o/s sliding door power window motor regulator	<i>Or</i>	\$225.70	✓
1 pc	Rear o/s fender <i>1625-70</i>	<i>R1</i>	\$1,850.90	✓
1 pc	Rear o/s fender glass moulding	<i>mm</i>	\$155.60	✓
1 pc	Rear bumper	<i>Sm</i>	\$1,550.70	X
1 pc	Rear o/s bumper side retainer	<i>Sm</i>	\$103.10	X
	<i>Rear o/s fender inner garnish 8725.60</i>	<i>mg cm</i>	\$9,738.30	✓
	<i>Rear o/s door frame rubber 237.60</i>	<i>nd/dis</i>	\$2,434.58	✓
		Less 25 %	\$7,303.72	

S Nett

20 pcs	Bumper clip	\$2.50	<i>nn</i>	\$50.00	X
1 pc	Rear o/s fender glass sealant		<i>mm</i>	\$40.00	✓
				\$90.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,600.00 *Good*

To putty & spray paint rear accident affected portion.

\$1,400.00 *Good*

balance c/f \$10,393.72

MR 7523 M

balance b/f \$10,393.72

Labour Charges

check/reconnect wiring.

\$45.00 201

To spray anti rust on accident affected portion.

\$120.00 601

Remove/refit rear o/s door glass & mechanism to new door

\$220.00 601

Remove/refit roof lining to facilitate repair

\$150.00

Remove/refit floor carpet & cushion seat to facilitate repair.

\$180.00

\$11,108.72

11,831.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: