



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2007063
INV Date 19/10/2020
Reference CS/SMO20010719/Uyd3q2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SKE 87T
Insured Veh. SMJ 9287Z
Claim No. CMTD2002898/RUC
Policy No.
Accident Date 02/10/2020
Inspection Date 09/10/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010719/Uyd3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 19-10-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMJ 9287Z	Veh. Inspected	SKE 87T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002898/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/10/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GB71089527	Colour	WHITE
Odometer	17982	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	TRIANGLE	6 mm
L/H Front Tyre	195/60 R15	TRIANGLE	6 mm
R/H Rear Tyre	195/60 R15	TRIANGLE	6 mm
L/H Rear Tyre	195/60 R15	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2020	Inspection Date	09/10/2020
Survey held at	BLK 10 KAKI BUKIT ROAD 2#01-05		
Repairer	PROFI AUTOMOTIVE		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
- B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 87T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR PANEL RH	TO REPAIR SEE LABOUR	1,258.00	-
1	FRONT DOOR TAPE RH	NOT NECESSARY	48.00	-
1	FRONT DOOR LOCK RH	NOT NECESSARY	321.00	-
1	REAR DOOR PANEL	TO REPAIR SEE LABOUR	1,510.00	-
1	REAR DOOR TAPE RH	NOT NECESSARY	48.00	-
1	REAR DOOR LOCK RH	NOT NECESSARY	324.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,259.00	-
1	REAR AXLE BEAM	NOT NECESSARY	1,400.00	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	495.00	-
1	REAR WHEEL HUB AND BEARING RH	NOT NECESSARY	421.00	-
	LESS 20% DISCOUNT		-1,416.80	-
			5,667.20	-
<u>SPECIAL NETT ITEMS</u>				
1	RIM (SN)	TO REPAIR SEE LABOUR	500.00	-
1	BT BRAKE FLUID (SN)	NOT NECESSARY	60.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	100.00	-
			660.00	-
<u>LABOUR</u>				
	CHECK WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	120.00	-
	REMOVE ,REFIT GARNISH ,TRIM AND LINING.	NOT NECESSARY	150.00	-
	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.		150.00	60.00
	TRANSFER PARTS ,ATTACHMENT FROM OLD FRONT DOOR TO NEW.	NOT NECESSARY	200.00	-
	TRANSFER PARTS ,ATTACHMENT FROM OLD SLIDING DOOR TO NEW .	NOT NECESSARY	200.00	-
	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS.	NOT NECESSARY	200.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT DOOR PANEL RH,REAR DOOR PANEL ,REAR FENDER RH AND RIM .	NOT NECESSARY	1,200.00	240.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	800.00
	APPLY ANTI-RUST ON AFFECTED AREAS.		120.00	-
			3,540.00	1,100.00
GRAND TOTAL			9,867.20	1,100.00
RECOMMENDED COST OF REPAIRS				1,100.00

Report Ref No. CS/SMO20010719/Uyd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 87T

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 87T

RE-INSPECTION

