

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010720/KRA3Q2
Date: 20/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070010017
Claimant Vehicle No :	SDW755L	Insured Vehicle No :	SMS3376S
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	0069446879SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW755L		
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Engine No:	FB20YC34483
Reg. Date:	22/02/2018 (Man. Year: 2017)	Chassis No:	JF1GT7KL5JG028083
Colour:	Metallic Pearl White	Odometer:	47979 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,588.60	1,019.04	4,569.56	81.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	730.00	2,270.00	75.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,588.60	1,749.04	6,839.56	79.64
Approved Total (Overridden) (S\$)		1,400.00		

(S\$)	8,588.60	1,400.00	7,188.60	83.70
+ GST 7.00/7.00% (S\$)	601.20	98.00	503.20	83.70
Nett Amount (S\$)	9,189.80	1,498.00	7,691.80	83.70
+ Car Rental (3.0 x S\$130.00/day) (S\$)		390.00		
Nett Liability (S\$)		1,888.00		

INSPECTION

Date of Assignment: 06/10/2020

Date Inspected: 06/10/2020

Estimated Period of Repair: 3.0 days

 Inspected At: Yee Auto Pte Ltd (HQ)
 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY
 Singapore 575722
Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Mtg Cracked	968.50 F	*600.20 FL	
2	1		*REAR BUMPER REINFORCEMENT	Bent	585.00 F	*388.50 FL	
3	1		*REAR BUMPER BRACKET LH (LOWER)	Serviceable	62.20 F	*- FL	
4	1		*REAR BUMPER BRACKET RH (LOWER)	Serviceable	62.20 F	*- FL	
5	1		*REAR BUMPER SIDE RETAINER -LH	Serviceable	95.60 F	*- FL	
6	1		*REAR BUMPER SIDE RETAINER -RH	Serviceable	95.60 F	*- FL	
7	1		*SET REAR BUMPER CLIP	Necessary	60.00 F	*60.00 FL	
8	1		*REAR BUMPER REFLECTOR -LH	Serviceable	155.10 F	*- FL	
9	1		*REAR BUMPER REFLECTOR -RH	Serviceable	155.10 F	*- FL	
10	1		*REAR END PANEL	Repair	755.10 F	*- FL	
11	1		*REAR TAILGATE	Repair	1,899.10 F	*- FL	
12	1		*REAR TAILGATE SUBARU EMBLEM	Not Necessary	82.00 F	*- FL	
13	1		*REAR TAILGATE XV EMBLEM	Not Necessary	88.00 F	*- FL	
14	1		*REAR BUMPER STEP GARNISH	Necessary	225.10 F	*225.10 FL	
15	1		*SET REVERSE SENSOR	Serviceable	300.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	5,588.60	1,273.80
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00	254.76
					Total Parts (\$)	5,588.60	1,019.04

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,400.00	300.00
2	TO PUTTY ,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,400.00	420.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	120.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	10.00
Gross Labour Cost (S\$)			3,000.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >