



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5788 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 03/10/2020
TP Veh Reg No: SMS3376S

Estimate No: ES2000089
Date: 05 Oct 2020
Policy No:
Veh Reg No: SDW755L
Make/Model: SUBARU XV 2.0I-S
EYESIGHT AWD CVT
Chassis No: JF1GT7KL5JG028083
Engine No: FB20YC34483
Reg. Date: 22/02/2018

Not Authorized

61 km @ 1400/5

Proving After Rain

3 days

Estimate Repair Cost to Vehicle No :SDW755L

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REVERSE SENSORS	300.00	1 SET	300.00	300.00
Spare Parts				
2 REAR BUMPER	968.50	1 PC	968.50	
3 REAR BUMPER REINFORCEMENT	585.00	1 PC	585.00	
4 REAR BUMPER BRACKET - LH (LOWER)	62.20	1 PC	62.20	
5 REAR BUMPER BRACKET - RH (LOWER)	62.20	1 PC	62.20	
6 REAR BUMPER SIDE RETAINER - LH	95.60	1 PC	95.60	
7 REAR BUMPER SIDE RETAINER - RH	95.60	1 PC	95.60	
8 REAR BUMPER CLIP	60.00	1 SET	60.00	
9 REAR BUMPER REFLECTOR - LH	155.10	1 PC	155.10	
10 REAR BUMPER REFLECTOR - RH	155.10	1 PC	155.10	
11 REAR END PANEL	755.10	1 PC	755.10	
12 REAR TAILGATE	1,899.10	1 PC	1,899.10	
13 REAR TAILGATE 'SUBARU' EMBLEM	82.00	1 PC	82.00	
14 REAR TAILGATE 'XV' EMBLEM	88.00	1 PC	88.00	
15 REAR BUMPER STEP GARNISH	225.10	1 PC	225.10	
			5,288.60	5,288.60
Labour				
16 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,400.00	1 JOB	1,400.00	
17 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,400.00	1 JOB	1,400.00	
18 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	
19 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	
			3,000.00	3,000.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9667 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 03/10/2020
TP Veh Reg No: SMS3376S

Estimate No: ES2000089
Date: 05 Oct 2020
Policy No:
Veh Reg No: SDW755L
Make/Model: SUBARU XV 2.0I-S
EYESIGHT AWD CVT
Chassis No: JF1GT7KL5JG028083
Engine No: FB20YC34483
Reg. Date: 22/02/2018

Estimate Repair Cost to Vehicle No :SDW755L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 8,588.60
			Add GST @ 7%	601.20
			Total Amount Payable	SS 9,189.80

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED EIGHTY NINE AND CENTS EIGHTY ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: