



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010723/T1Kyf3e2

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND
TOWER SINGAPORE 048623

Date : 17-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FP 5709B	Veh. Inspected	SJL 4764X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002923/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/10/2020

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SX4	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JSAGYA21S00119966	Colour	GREY
Odometer	422580	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/10/2020	Inspection Date	06/10/2020
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------