



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104470

INV Date 25/06/2021

Reference CC4/LPC20010724/Dgs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 2173R
Insured Veh. YP 9126G
Claim No. 20/20/20/VC00/023738
Policy No. Z/20/VC00/107781
Accident Date 03/10/2020
Inspection Date 06/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20010724/Dgs3q2 Date: 25/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9126G	Veh. Inspected	SHB 2173R	
Policy No.	Z/20/VC00/107781	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023738	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	06/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093534	Colour	YELLOW	
Odometer	470820 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	03/10/2020	Inspection Date	06/10/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2173R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	CUT	2,265.90	2,265.90
1	BONNET RUBBER (LH)	NOT NECESSARY	35.70	-
1	BONNET RUBBER (RH)	NOT NECESSARY	35.70	-
2	BONNET HINGE (LH/RH) @\$126.70	BENT	253.40	253.40
1	BONNET LOCK	NOT NECESSARY	142.40	-
1	BONNET ABSORBER (LH ONLY)	NOT NECESSARY	61.60	-
1	BONNET INSULATOR	NOT NECESSARY	202.50	-
10	BONNET INSULATOR CLIP	NOT NECESSARY	36.80	-
1	BONNET SEAL	NOT NECESSARY	31.90	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	15.00	-
1	BONNET CABLE	NOT NECESSARY	69.60	-
1	RADIATOR GRILLE H EMBLEM	NECESSARY	129.50	129.50
1	RADIATOR GRILLE	BROKEN	1,480.00	1,110.10
1	FRONT BUMPER COVER	TORN / CUT	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	NOT NECESSARY	379.20	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	588.40	-
2	FRONT BUMPER GRILLE (LH/RH) @\$149.20	NOT NECESSARY	298.40	-
1	FRONT BUMPER LIP	NOT NECESSARY	152.00	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$44.80	NOT NECESSARY	89.60	-
2	FRONT BUMPER BRACKET (LH/RH) @\$49.20	NOT NECESSARY	98.40	-
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	76.20	-
2	FRONT BUMPER GRILLE AIR DUCT (LH/RH) @\$126.20	NOT NECESSARY	252.40	-
2	HEADLAMP SUPPORT PANEL ASSY @\$907.40	BENT (1 PCS ONLY)	1,814.80	907.40
2	HEADLAMP (LH/RH) @\$2776.00	MTG BROKEN	5,552.00	2,776.00
2	HEADLAMP SUPPORT TOP COVER @\$222.60	CRACKED (1 PCS ONLY)	445.20	222.60
1	RADIATOR	BENT	1,637.20	708.50
1	RADIATOR GUARD (LH/RH) @\$76.50	NOT NECESSARY	153.00	-
1	COOLANT	NOT NECESSARY	45.00	-
2	RADIATOR FAN BLADE ,COWLING ,MOTOR ASSY @\$1194.20	MTG BROKEN	2,388.40	792.95

Report Ref No. CC4/LPC20010724/Dgs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR EXPANSION TANK	NOT NECESSARY	163.80	-
1	HORN UNIT (LH/RH) @\$72.30	NOT NECESSARY	144.60	-
1	HORN WIRE	NOT NECESSARY	156.60	-
1	AIR CLEANER COVER	NOT NECESSARY	228.60	-
1	AIRCON CONDENSER	BENT	947.80	947.80
1	DASHBOARD COMPLETE	NOT NECESSARY	2,240.00	-
1	INTER COOLER	DAMAGED	1,032.50	1,032.50
1	ENGINE TOP COVER	NOT NECESSARY	321.70	-
	LESS 20% DISCOUNT		-5,003.60	-2,439.77
			20,014.40	9,759.08
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT NO.PLATE TRIM COVER (SN)	CUT / BENT	30.00	25.00
			55.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,400.00	600.00
	SPRAY PAINTING CHARGE.		1,200.00	500.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		140.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	REMOVE/REFIX ENGINE .	NOT NECESSARY	600.00	-
	REMOVE/REFIX DASHBOARD .	NOT NECESSARY	350.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,700.00	1,300.00
GRAND TOTAL			24,769.40	11,109.08

Report Ref No. CC4/LPC20010724/Dgs3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,800.00
---	--	--	-----------------

Report Ref No. CC4/LPC20010724/Dgs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 2173R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 2173R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 2173R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

