

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 5-Oct-20

INSURANCE: Lonpac

MODEL: HYUNDAI I40

VEHICLE NO.: SHB 2173 R

CC4/LPC 20010724/10pgs<sup>3</sup>

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>Cwd</i>	1	\$2,265.90	\$2,265.90
BONNET RUBBER (LH) <i>HH</i>	1	\$35.70	\$35.70
BONNET RUBBER (RH) <i>HH</i>	1	\$35.70	\$35.70
BONNET HINGE (LH/RH) <i>ST</i>	2	\$126.70	\$253.40
BONNET LOCK <i>ST</i>	1	\$142.40	\$142.40
BONNET ABSORBER (LH ONLY) <i>HH</i>	1	\$61.60	\$61.60
BONNET INSULATOR <i>HH</i>	1	\$202.50	\$202.50
BONNET INSULATOR CLIP 10 PCS <i>HH</i>	1	\$36.80	\$36.80
BONNET SEAL <i>HH</i>	1	\$31.90	\$31.90
BONNET INSULATOR CLIPS <i>HH</i>	1	\$15.00	\$15.00
BONNET CABLE <i>HH</i>	1	\$69.60	\$69.60
RADIATOR GRILLE H EMBLEM <i>HH</i>	1	\$129.50	\$129.50
RADIATOR GRILLE <i>broken</i> 1110-10	1	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>form / Cwd</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>HH</i>	1	\$379.20	\$379.20
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$588.40	\$588.40
FRONT BUMPER GRILLE (LH/RH) <i>HH</i>	2	\$149.20	\$298.40
FRONT BUMPER LIP <i>HH</i>	1	\$152.00	\$152.00
FRONT BUMPER BRACKET TOP (LH/RH) <i>HH</i>	2	\$44.80	\$89.60
FRONT BUMPER BRACKET (LH/RH) <i>HH</i>	2	\$49.20	\$98.40
FRONT BUMPER RETAINER MOUNTING <i>HH</i>	1	\$76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (LH/RH) <i>HH</i>	2	\$126.20	\$252.40
HEADLAMP SUPPORT PANEL ASSY <i>2 ST</i>	2	\$907.40	\$1,814.80
HEADLAMP (LH/RH) <i>many broken photo</i>	2	\$2,776.00	\$5,552.00
HEADLAMP SUPPORT TOP COVER <i>crack</i>	2	\$222.60	\$445.20
RADIATOR <i>2 ST</i> 708.50	1	\$1,637.20	\$1,637.20
RADIATOR GUARD (LH/RH) <i>HH</i>	2	\$76.50	\$153.00
COOLANT <i>HH</i>	1	\$45.00	\$45.00
RADIATOR FAN BLADE, COWLING, MOTOR ASSY <i>many broken</i>	2	\$1,194.20	\$2,388.40
RADIATOR EXPANSION TANK <i>HH</i> 792.95	1	\$163.80	\$163.80
HORN UNIT (LH/RH) <i>HH</i>	2	\$72.30	\$144.60
HORN WIRE <i>HH</i>	1	\$156.60	\$156.60
AIR CLEANER COVER <i>HH</i>	1	\$228.60	\$228.60
AIRCON CONDENSER <i>2 ST</i>	1	\$947.80	\$947.80
DASHBOARD COMPLETE <i>HH</i>	1	\$2,240.00	\$2,240.00
INTER COOLER <i>2 Dem</i>	1	\$1,032.50	\$1,032.50
ENGINE TOP COVER <i>HH</i>	1	\$321.70	\$321.70
SUB TOTAL			\$25,018.00
LESS 20%			\$5,003.60
DISCOUNTED TOTAL			\$20,014.40
FRONT NUMBER PLATE <i>HH</i> SN	1	\$25.00	\$25.00



FRONT NO. PLATE TRIM COVER Cng	45	SN	1	\$30.00	\$30.00
SUB TOTAL					\$55.00
<b>Labour Charge</b>					
Panel Beating		1	\$1,400.00	\$1,400.00	
Spray Painting Charge		1	\$1,200.00	\$1,200.00	
Wiring Charge		1	\$160.00	\$160.00	
Tuff Kote		1	\$140.00	\$140.00	
Towing Charge		1	\$80.00	\$80.00	
Remove/Refix Radiator		1	\$90.00	\$90.00	
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	
Remove/Refix Engine	1300.00	1	\$600.00	\$600.00	
Remove/Refix Dashboard		1	\$350.00	\$350.00	
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	
TOTAL LABOUR					\$4,700.00
ESTIMATE TOTAL					\$ 24,769.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

05/10/2016 @ 1630hrs

06

Hot Antenna

2/sml

7 dgs.

Man

LKK Auto

11109.08

4/5 8800/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: