

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

TP 1st Cap.
Xiao Tong

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amo
AIRCON CONDENSER Bent	1	632.30	✓ 632.30
AIRCON CONDENSER ALUMINIUM PIPE } New	1	175.00	✗ 175.00
AIRCON CONDENSER DISCHARGE HOSE } New	1	385.00	✗ 385.00
AIRCON CONDENSER FAN BLADE New	1	62.00	✗ 62.00
AIRCON CONDENSER FAN COWLING Cured	1	135.00	✓ 135.00
AIRCON CONDENSER FAN MOTOR xbe new	1	315.00	✗ 315.00
AIRCON CONDENSER SUCTION HOSE } New	1	550.00	✗ 550.00
AIRCON OUTSIDE TEMPERATURE SENSOR } New	1	50.00	✗ 50.00
AUTO TRANSMISSION OIL COOLER Dented	1	980.00	✓ 980.00
AUTO TRANSMISSION OIL COOLER DISCHARGE HOSE } New	1	129.00	✗ 129.00
AUTO TRANSMISSION OIL COOLER SUCTION HOSE } New	1	129.00	✗ 129.00
FRONT AIR CLEANER BOX (BASE) } New	1	145.00	✗ 145.00
FRONT AIR CLEANER BOX (COVER) } New	1	120.00	✗ 120.00
FRONT AIR CLEANER BOX AIR DUCT } New	1	105.00	✗ 105.00
FRONT BATTERY (BASE) } New	1	95.00	✗ 95.00
FRONT BATTERY (COVER) } New	1	27.50	✗ 27.50
FRONT BATTERY TOP BRACKET } New	1	18.50	✗ 18.50
FRONT BONNET Distorted	1	721.50	✓ 721.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

FRONT BONNET HINGES L/R <i>xe n</i>	2	43.80	+	87.60
FRONT BONNET INNER CENTER RUBBER MOULDING <i>xe n</i>	1	65.00	+	65.00
FRONT BONNET INNER TOP RUBBER MOULDING <i>xe n</i>	1	70.00	+	70.00
FRONT BONNET INSULATOR <i>xe n</i>	1	145.00	+	14.00
FRONT BONNET MECHANISM LOCK <i>Demd</i>	1	78.60	✓	78.60
FRONT BONNET MECHANISM LOCK GARNISH <i>ut</i>	1	28.00	✓	28.00
FRONT BUMPER <i>Distorted</i>	1	976.00	✓	976.00
FRONT BUMPER FOGLAMP BRACKET L/R <i>xe n</i>	2	35.00	+	70.00
FRONT BUMPER FOGLAMP L/R <i>could</i>	2	275.50	✓	551.00
FRONT BUMPER FOGLAMP SIDE GARNISH L/R <i>xe n</i>	2	65.00	+	130.00
FRONT BUMPER LOWER GRILLE <i>Dehd</i>	1	125.30	✓	125.30
FRONT BUMPER NUMBER PLATE GARNISH <i>could</i>	1	52.00	✓	52.00
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	187.00	✓	187.00
FRONT BUMPER SIDE RETAINER L/R <i>m</i>	2	20.00	✓	40.00
FRONT FENDER INNER SHIELD COVER L/R <i>xe n</i>	2	100.00	+	200.00
FRONT FENDER L/R <i>Repis</i>	2	575.60	+	1,151.00
FRONT FENDER TOP GARNISH L/R <i>xe n</i>	2	55.00	+	110.00
FRONT GRILLE 'EURO R' EMBLEM <i>Nu</i>	1	50.00	✓	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

FRONT GRILLE 'LOGO' EMBLEM <i>Ne</i>	1	23.40	✓	23.40
FRONT GRILLE (BASE) <i>crackd.</i>	1	280.50	✓	280.50
FRONT GRILLE (MOULDING) <i>Ne</i>	1	285.00	+	285.00
FRONT GRILLE INNER TOP GARNISH <i>Delvond</i>	1	95.60	✓	95.60
FRONT HEADLAMP L/R <i>crackd.</i>	2	814.70	✓	1,629.40
FRONT HEADLAMP LOWER BRACKET L/R <i>Ne</i>	2	40.00	+	80.00
FRONT HORN <i>Ne</i>	1	48.60	+	48.60
FRONT RESONATOR BOX <i>crackd.</i>	1	240.00	✓	240.00
FRONT RESONATOR BOX AIR DUCT <i>Ne</i>	1	45.00	+	45.00
FRONT RESONATOR BOX AIR INTAKE TUBE <i>Ne</i>	1	55.00	+	55.00
FRONT SUPPORT PANEL <i>crackd.</i>	1	680.00	✓	680.00
FRONT SUPPORT PANEL INNER RUBBER GUIDE STOPPER <i>Ne</i>	4	12.50	+	50.00
RADIATOR <i>crackd.</i>	1	1382.60	✓	1,382.60
RADIATOR FAN BLADE <i>Ne</i>	1	58.40	+	58.40
RADIATOR FAN COWLING <i>crackd.</i>	1	125.00	✓	125.00
RADIATOR FAN MOTOR <i>Ne</i>	1	350.00	+	350.00
RADIATOR LOWER HOSE <i>Ne</i>	1	45.00	+	45.00
RADIATOR SPARE TANK <i>Ne</i>	1	62.50	+	62.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

RADIATOR SPARE TANK HOSE	1	25.50	+	25.50
RADIATOR TOP BRACKET L/R	2	19.50	+	39.00
RADIATOR TOP HOSE	1	48.00	+	48.00
RADIATOR WATER TEMPERATURE SENSOR	1	46.70	+	46.70
REAR BOOTLID	1	750.00	+	750.00
REAR BOOTLID 'ACCORD' EMBLEM	1	30.00	✓	30.00
REAR BOOTLID 'LOGO' EMBLEM	1	26.30	✓	26.30
REAR BOOTLID HINGES GARNISH L/R	2	26.50	+	53.00
REAR BOOTLID HINGES L/R	2	80.00	+	160.00
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	2	12.00	+	24.00
REAR BOOTLID INNER TRIM GARNISH	1	205.00	+	205.00
REAR BOOTLID LOCK STRIKER	1	27.50	+	27.50
REAR BOOTLID MECHANISM LOCK	1	269.00	+	269.00
REAR BOOTLID MECHANISM LOCK GARNISH	1	112.60	+	112.60
REAR BOOTLID REFLECTOR INNER RUBBER GASKET L/R	2	18.00	+	36.00
REAR BOOTLID REFLECTOR L/R	2	215.00	X	430.00
REAR BOOTLID WEATHER STRIP	1	115.00	+	115.00
REAR BUMPER	1	950.00	✓	950.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

REAR BUMPER REFLECTOR L/R	<i>cracked.</i>	2	50.00	✓	100.00
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	25.00	✓	50.00
REAR BUMPER UNDER COVER	<i>tom.</i>	1	135.00	✓	135.00
REAR END PANEL	<i>Distorted.</i>	1	550.00	✓	550.00
REAR END PANEL INNER TOP GARNISH	<i>Dehnd</i>	1	80.00	✓	80.00
REAR EXHAUST HEAT SHIELD COVER	<i>new</i>	1	85.00	+	85.00
REAR EXHAUST RUBBER MOUNTING	<i>new</i>	2	16.50	+	33.00
REAR EXHAUST SILENCER BOX	<i>Best</i>	1	1208.80	✓	1,208.80
REAR FENDER INNER SHIELD COVER L/R	<i>new</i>	2	140.00	+	280.00
REAR FENDER INNER TRIM GARNISH L/R	<i>cracked</i>	2	235.00	✓	470.00
REAR FENDER L/R	<i>RH Buckled</i>	2	1030.80	<i>1030.80</i>	2,061.60
REAR FLOOR JACK PANEL	<i>Distorted</i>	1	420.00	✓	420.00
REAR FLOOR PANEL	<i>Distorted.</i>	1	1514.30	✓	1,514.30
REAR FLOOR PANEL SPONGE COMPARTMENT TRAY	<i>cracked</i>	1	180.00	✓	180.00
REAR FLOOR PANEL TOP BOARD COVER	<i>cracked</i>	1	325.30	✓	325.30
REAR FUEL TANK TOP COVER	<i>new</i>	1	110.50	x	110.50
REAR RH EXTENSION MEMBER	<i>Repair</i>	1	690.50	x	690.50
REAR TAILLAMP INNER RUBBER GASKET L/R	<i>new</i>	2	18.00	✓	36.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

REAR TAILLAMP L/R	LH ut, RH cracked	2	250.00	✓	500.00
REAR TAILLAMP LOWER BRACKET L/R	new	2	15.00	X	30.00
REAR WINDSCREEN MOULDING	new	1	89.00	✓	89.00
Subtotal before discount					26,724.10
Percentage discount 20%					5,344.82
Sub-total 1					21,379.28
FRONT BATTERY	new	1	220.00	X	220.00
FRONT BONNET INNER CENTER RUBBER MOULDING CLIPS - SET		1	20.00	X	20.00
FRONT BONNET INNER TOP RUBBER MOULDING CLIPS - SET		1	20.00	X	20.00
FRONT BONNET INSULATOR CLIPS - SET		1	50.00	X	50.00
FRONT BUMPER CLIPS - SET	new	1	50.00	30	50.00
FRONT BUMPER FOGLAMP LED BULB - SET	new	1	350.00	X	350.00
FRONT BUMPER LOWER SPOILER	Delivered	1	1250.00	800	1,250.00
FRONT BUMPER NUMBER PLATE	Cracked	1	25.00	✓	25.00
FRONT BUMPER NUMBER PLATE HOLDER	Delivered	1	50.00	30	50.00
FRONT FENDER INNER SHIELD COVER CLIPS L/R - SET	new	2	30.00	X	60.00
FRONT GRILLE INNER TOP GARNISH CLIPS - SET	new	1	30.00	✓	30.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	new	1	50.00	X	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045

Date in : 04/10/2020

Vehicle Num. : SJG5236Z

Model : HONDA ACCORD 2.0 A

Chassis/Eng# : CL73304409/K20A6055064

REAR BOOTLID NUMBER PLATE	1	25.00	X	25.00
REAR BOOTLID NUMBER PLATE HOLDER	1	50.00	X	50.00
REAR BOOTLID REVERSE CAMERA	1	800.00	X	800.00
REAR BOOTLID TOP SPOILER	1	500.00	X	500.00
REAR BUMPER CLIPS - SET	1	50.00	30	50.00
REAR BUMPER LOWER SPOILER	1	1350.00	750	1,350.00
REAR BUMPER REVERSE SENSOR - SET	1	350.00	200	350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	10	30.00
REAR EXHAUST MUFFLER	1	180.00	X	180.00
REAR FENDER INNER SHIELD COVER CLIPS L/R - SET	2	30.00	X	60.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	50.00	60	100.00
REAR FLOOR PANEL INSULATOR MAT	1	300.00	200	300.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	20	50.00
REAR WINDSCREEN SEALANT	1	80.00	60	80.00
Subtotal before discount				6,100.00
Percentage discount 0%				0.00
Sub-total 2				6,100.00
Parts-total				27,479.28

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOH SWEE HUAT
BLK 686B CHOA CHU KANG CRESCENT
#10-224
SINGAPORE 682686

Contact : 87771817

ESTIMATE

Repair Code : CLM15045
Date in : 04/10/2020
Vehicle Num. : SJG5236Z
Model : HONDA ACCORD 2.0 A
Chassis/Eng# : CL73304409/K20A6055064

LABOUR

- To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector
- To remove, change air con parts, vacuums, refill air con gas.
- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall windscreen (REAR)
- To remove, reinstall petrol tank. (to FR)
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.
- To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

X	80.00
120	160.00
30	100.00
80	100.00
120	150.00
✓	80.00
100	140.00
1000	1,600.00
80	1,400.00
80	100.00
2400	3,800.00
✓	120.00

Labour Total

7,830.00

Parts & Labour Total

35,309.28

*** This is a computer-generated document which requires no signature.***

page 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 19574.92
L/S: 13K (Nett Value)

Nett Value: 13K.

13K

18 Days