



FORZA AUTOHAUS PTE LTD

COMPANY REG NO.: 201833292C

GST NO.: 201833292C

39 Woodlands Close, #01-34/35, Mega @ Woodlands,
Singapore 737856

+65 6278 1889 enquiry@forzaauto.sg

ESTIMATE

87 LEASING
206 JALAN EUNOS #01-56, EUHABITAT Singapore
419547

Contact : 91118531

Code : C100034

Date in : 07/10/2020

Vehicle Num. : SGF2824L

Model : TOYOTA PICNIC AUTO

Chassis/Eng# : JTEGH223B200021573/1AZ5378681

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER / CR4	1	320.00	320.00
REAR END PANEL x R	1	428.00	428.00
REAR END PANEL TOP COVER x SUC	1	386.00	386.00
Subtotal before discount			1,134.00
Percentage discount 25%			283.50
Sub-total 1			850.50
REAR BUMPER CLIPS SET / Npc	1	30.00	30.00
REVERSE SENSOR / short	1	150.00	150.00
Subtotal before discount			180.00
Percentage discount 0%			0.00
Sub-total 2			180.00
Parts-total			1,030.50

LABOUR

Description	Price
TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	100.00 30
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	600.00 300
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	700.00 300
Repair day - 2 days	
4/5	
After paint photo	
Sun Pin (LKIC)	
01/10/2020	
TP without prejudice.	
Labour Total	1,400.00
Parts & Labour Total	2,430.50

LKS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: