

Vehicle no. : SLR 4535K
 Model : Mazda 3
 Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
LIST ITEMS:-			\$
1	1 pc	LH front fender ✓ DD	450
2	1 pc	LH front fender inner shield ✓ TN	155
3	1 pc	Front bumper ✓ BR	966
4	1 pc	bumper reinforcement ✗ NN	510
5	1 pc	front bumper side retianer ✓ BR	25
6	1 pc	front bumper fog lamp cover ✓ CUT	68
	1pc	front bumper fog lamp ✗ NN	248
7	1 pc	Bonnet ✓ DD	1150
8	1 pc	Bonnet lock ✗ NN	225
9	1pc	RH headlamp ✓ CUT	1100
10	1 pc	front right door ✓ DD	1200
11	1 pc	front right side mirror assy ✗ Repair	750
			6847
Less 20%			1369.4
Special Nett			5477.6
1	1	front RH rim ✓ CUT	350

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
B/F			
LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts	800 600
2		To anti-rust	100 30
3		to realign headalamp focus	40 30
4		to remove and reinstall front right door components (include wheel alignment)	150 50 110
5		To putty and spray-paint of affected areas	1000 800
			2090

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Steve (LKK)
 Without Prejudice
 08/10/20, 11.00am
 5 repair days
 L/S
 Resurvey after spray