



Case Details

Case Reference Number : BUS/09/20/5039

Company Type : SMRT Buses Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-12787-ID

Accident Date and Time : 29/09/2020 11:04 PM

Vehicle Registration Number : SMB253Y

Assigned By : Claiming Case Owner Team

Vehicle Age(In Months) : 101

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	BODY LH	6010005	PANEL, SIDE: L11, FOR MAN A22 BUS	1	1,092.50	1,092.50	10.00	983.25	Replace	1	983.2	Replace	✓ / PD
Standard	Main	Body	6010060	COVER: REAR TAIL LAMP, LH, FOR MAN A22 BUS	1	974.70	974.70	10.00	877.23	Replace	1	877.2	Replace	✓ / CKM
Standard	Main	VE	6010298	LAMP, STOP: LED (MAN BUS)	1	1,141.70	1,141.70	10.00	1,027.53	Replace	1	1,027	Replace	✓ / CKM
Standard	Main	VE	6010299	LAMP, INDICATOR: LED (MAN BUS)	1	1,274.10	1,274.10	10.00	1,146.69	Replace	1	1,146	Replace	✓ / CKM
Total Spare Part Cost									4,034.70	Surveyor Total		4,034.70		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,227.76	Final Sur Total		3,227.76		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	795	
Total:			1,060.00	795.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	786.00	616	
Total:			786.00	616.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,227.76	3,227.76
Total Labour Cost	1,060.00	795.00
Total Spray Painting	786.00	616.00
Other	0.00	0.00
Overall Total	5,073.76	4,638.76
Lump Sum Repair Option		
Lump Sum Total	5,050.00	4,638.76
Surveyor Approved Amount		4,638.76
No of Repair Days*	4	3 3 days
Remarks	-	4/5 Surveyor Remarks
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	05/10/2020	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: