

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 08 Oct 2020

Preliminary Advice

Insured Vehicle No	: YP8768K		
TP Vehicle No	: SLH7302Z	Accident Date	: 03/10/2020
Make	: HONDA SHUTTLE HYBRID	Assignment Date	: 06/10/2020
Date of Inspection	: 06/10/2020	Est. Duration of Repair	: 6
Inspection At	: LION CITY RENTAL (JALAN LAM HUAT) (HQ) 60 JALAN LAM HUAT, 04-35/36 CARROS CENTRE SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,192.56
Revised Amount	:S\$	12,300.96
Check Items (Estimated)	:S\$	160.00
Total	:S\$	12,460.96

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :