

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20010750/RQD3N2**Date:** 12/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00095712000

Claimant Vehicle No : SMS8875K **Insured Vehicle No :** YN7796X

Date of Loss: 02/10/2020 Nature of Claim: TP Claim No: SNM20D203707/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMS8875K**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B5576242

Reg. Date: 19/03/2020 (Man. Year: 2019) Chassis No: RU11326202

Colour: White Odometer: 4049 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,293.84	2,211.84	82.00	3.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	830.00	200.00	19.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,323.84	3,041.84	282.00	8.48
+ GST 7.00/7.00% (S\$)	232.67	212.93	19.74	8.48
Nett Amount (S\$)	3,556.51	3,254.77	301.74	8.48

INSPECTION

Date of Assignment: 06/10/2020

Date Inspected: 08/10/2020 Inspected At: Mova Automotive Pte Ltd (FAN YOONG BRANCH)
15 Fan Yoong Road, CNG Singapore Centre
Singapore 629792

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS8875K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Cracked	1,715.10 FL	*1,715.10 FL
2	1		*HEADLAMP TOP MOULDING RH	Not Necessary	85.00 FL	*- FL
3	1		*FRONT BUMPER	Scratched	801.70 FL	*801.70 FL
4	1		*FRONT BUMPER RETAINER RH	Not Necessary	17.50 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
6	1		*FOG LAMP GARNISH RH	Scratched	60.00 FL	*60.00 FL
7	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT FENDER ARCH MOULDING RH	Scratched	153.00 FL	*153.00 FL
					Sub Total (\$\$)	2,867.30 2,764.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	573.46 552.96
					Total Parts (\$\$)	2,293.84 2,211.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN FRONT FENDER RH,REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	400.00	300.00
2	SPRAY PAINT FRONT BUMPER,FRONT FENDER RH (PEARL COLOUR)	New	600.00	500.00
3	CHECK WIRING & FOCUS HEADLIGHT	New	30.00	30.00
Gross Labour Cost (\$\$)			1,030.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >