

# ESTIMATE FOR SJM2424K

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 45274  
Reg No/Reg Date SJM2424K / 22/09/2017  
Date In/Mileage / 0  
Chassis No WDD2130422A226930  
Engine No 27492030990041  
Make/Model MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE  
Colour/Trim 029 992 Selenite Gr/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	29/09/2020/ 20:26	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :1700052956 // 29-09-2020 DRIVE IN:29-09-2020 // TP CAR NO:PC1794E (CHINA TAIPING INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				96.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1920.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER				1500.00
M RH/F FENDER	1.00	1020.74	00.00	1020.74
M RH/F INTERMEDIATE LAYER	1.00	11.75	00.00	11.75
M RH/F WHEEL ARCH	1.00	121.13	00.00	121.13
M FRT BUMPER	1.00	1284.17	00.00	1284.17
M RH/F BUMPER BRACKET	1.00	8.95	00.00	8.95
M RH/F BOTTOM GRILLE	1.00	68.20	00.00	68.20
M RH/F BASIC MOUNTING FOR BUMPER	1.00	66.94	00.00	66.94
M RH/F OUTER PARKING SENSOR	1.00	178.75	00.00	178.75
M RH/F OUTER PARKING SENSOR SEAL	1.00	6.35	00.00	6.35
M RH/F HEADLAMP	1.00	3448.41	00.00	3448.41

Tanphn 97495749  
wp 7/10/20 330pm.  
Resurvey before paint  
tanphn@10ants.com  
05 days

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
WD: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cvcyclecarriage.com.sg

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Confirmed & accepted by

Authorized signatory and company stamp

7% GST on 10111.39  
Total Payable 10,819.19

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.