



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SJM2424K

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Taufikh

Vehicle & Document Information

WIP No **45274**
Reg No/Reg Date **SJM2424K / 22/09/2017**
Date In/Mileage **07/10/2020/ 31295**
Chassis No **WDD2130422A226930**
Engine No **27492030990041**
Make/Model **MB/MB E 200 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator	
WC000668	Credit	29/10/2020/ 19:35	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1700052956 // 29-09-2020
DRIVE IN: 29-09-2020 // TP CAR NO: PC1794E (CHINA TAIPING INS)
DATE IN/DATE SURVEY: 07-10-2020 // LKK TAUFIKH
BY/AUTHORIZED ON : CECILIA LOW // 06-10-2020

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT
SUPPORT ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER & FRONT RIGHT FENDER

X RH/F FENDER

1.00 1020.74 00.00 1020.74

X FRT BUMPER

1.00 1284.17 00.00 1284.17

X RH/F BOTTOM GRILLE

1.00 68.20 00.00 68.20

X RH/F OUTER PARKING SENSOR

1.00 178.75 00.00 178.75

X RH/F OUTER PARKING SENSOR SEAL

1.00 6.35 00.00 6.35

X RH/F HEADLAMP

1.00 3448.41 00.00 3448.41

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **8,642.62**
7% GST on **8642.62** **604.98**
Total Payable 9,247.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany