



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2008110
INV Date 03/12/2020
Reference CC6/LPC20010756/Kba3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SMK 2101S
Insured Veh. GBH 6466J
Claim No. 20/20/20/VC05/023736
Policy No. Z20VC05005829
Accident Date 02/10/2020
Inspection Date 05/10/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC20010756/Kba3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 03-12-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 6466J	Veh. Inspected	SMK 2101S
Policy No.	Z20VC05005829	Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023736	Excess (\$)	0.00
Assign From		Assign Date	05/10/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK82001145	Colour	METALLIC DARK BLUE
Odometer	28612	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2020	Inspection Date	05/10/2020
Survey held at	R C AUTO BLK 18 SIN MING INDUSTRIAL ESTATE SECTOR A #01-43 SINGAPORE 575676		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 2101S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTLID	BENT	970.00	970.00
1	REAR BOOTLID WINDSCREEN MLDG	NECESSARY	50.00	50.00
1	REAR BUMPER	NECESSARY	780.00	780.00
1	REAR BOOTLID EMBLEM (HONDA)	NECESSARY	60.00	60.00
1	REAR BOOTLID EMBLEM (SHUTTLE)	NECESSARY	58.00	58.00
	LESS 20% DISCOUNT		-383.60	-383.60
			1,534.40	1,534.40
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSORS (SN)	SHORTED	250.00	200.00
			250.00	200.00
	<u>LABOUR</u>			
	SPRAY PAINTING .		500.00	450.00
	TO REINSTALL TAILGATE WINDSCREEN .		150.00	120.00
	LABOUR CHARGES TO REPLACE ABOVE PARTS.		600.00	500.00
	TO CHECK WIRING .		30.00	20.00
			1,280.00	1,090.00
	GRAND TOTAL		3,064.40	2,824.40
	RECOMMENDED COST OF REPAIRS			2,824.40

Report Ref No. CC6/LPC20010756/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 2101S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

