



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV08995/MARCUS CHIA SEE WEI Reg No/Reg Date SMD1960Y / 07/08/201 Date In/Mileage / 0 Chassis No GF7W0402085 Engine No 4J11YP9394 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim COO / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	06/10/2020/ 13:45	QUD	247 / DonBong	58165

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24
M BRKT,FR BUMPER SIDE,LWR RH	1.00	6.00	23.00	4.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# Estimate

SURVEYOR NAME: Tanpin 97495749SURVEYOR SIGNATURE: [Signature]DATE: 07/10/20 @ 2:15 pmREMARKS: Not Authorise, Revert.

Ex: to be advise Resurvey before print  
Tanpin @ 11am to 12pm  
06 days

Confirm &amp; accepted by

Nett	7,382.10
7% GST on	516.75
<b>Total Payable</b>	<b>7,898.85</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV08995/MARCUS CHIA SEE WEI Reg No/Reg Date SMD1960Y / 07/08/201 Date In/Mileage / 0 Chassis No GF7W0402085 Engine No 4J11YP9394 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim COO / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	06/10/2020/ 13:45	QUD	247 / DonBong	58165			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								900 1350.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT BONNET, 45°								
RH FRONT FENDER, FRONT BUMPER FACE								<del>700</del> 1050.00
E PNT98000								
PAINT WORK SPRAY FRONT BONNET, RH FRONT FENDER 35°								
AND AFFECTED PORTION and f bumper.								X 80.00
M SUNDRY								
APPLY BODY SEALANT								30.
A 54900099								
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM 0.60								160 240.00
M SUNDRY								
RE-APPLY ZERTONA BODY COATING								40. 80.00
M SUNDRY								
PERFORM RUST PREVENTION								✓ 120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								20 50.00
M SUNDRY								
SUNDRIES								
M	HEADLAMP ASSY,RH				1.00	2125.00	23.00	<del>cr</del> 1636.25
M	FENDER,FR RH				1.00	688.00	23.00	<del>bt</del> 529.76
M	HOOD				1.00	975.00	23.00	<del>bt</del> 750.75
M	HINGE,HOOD,LH				1.00	68.00	23.00	Ky 52.36
M	HINGE,HOOD,RH				1.00	68.00	23.00	Rv 52.36
M	LATCH,HOOD				1.00	76.00	23.00	Ky 58.52
M	ENGINE HOOD EMBLEM				1.00	80.00	23.00	ney 61.60
M	BRACKET,FR BUMPER SIDE,LH				1.00	18.00	23.00	X 13.86
M	BRACKET,FR BUMPER SIDE,RH				1.00	18.00	23.00	? 13.86
M	FACE,FR BUMPER				1.00	859.00	23.00	? 661.43
M	COVER,FR BUMPER				1.00	294.00	23.00	? 226.38
M	GARNISH,FR BUMPER,RH				1.00	75.00	23.00	? 57.75
M	GARNISH,FR BUMPER SIDE				1.00	48.00	23.00	wt ✓ 36.96
M	GARNISH,FR BUMPER SIDE				1.00	220.00	23.00	? 169.40

# Estimate

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.