



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SNM20D202382/GBG4776H/TANGHL2

Date: 20th October 2020

Our Ref: CS1/CTI20010766/Esd3s2

M/s China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLS 8713G
INSURED VEHICLE: GBG 4776H ACCIDENT DATE: 08/07/2020**

We thank you for your instruction on 30/09/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLS 8713G from M/s Kelvin Automotive Appraising Services.
- b) Final Repair Bill of SLS 8713G from M/s Apex Motoring.
- c) Singapore Accident Statement of Vehicle SLS 8713G.
- d) Colour damaged vehicle photographs of SLS 8713G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLS 8713G
Make & Model	: Honda Shuttle
Year of Registration	: 2017
Chassis Number	: GP71120320
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.