MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422/ 6745 4422 Fax: 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD			Quotation		
3 Anson Road #16-00		DATE	: 19.10.2020		
Springleaf Tower		VEH NO	: SMK2655K		
Singapore 079909		MODEL	: Honda Vezel		
Tel: 6389 - 6111	1 Chanchan	DOA	: 01.10.2020		
Fax: 6224 - 7478 / 7175		YR REF	: SLS3993Y		

Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SMK2655K (HONDA VEZEL)

<u>Item</u>	Description	_Qty	_	<u>Amt</u>	
NO	LIST ITEMS				
1	Front Bumper Debug	- 1		880.00	
2	Front Bumper Clips	1 set		30.00	/
3	Front Bumper Side Holder - RH	1		23.60	X.
4	Front Bumper Lower Garnish	1		351.00	
5	Front Bumper Fog Lamp Cover - RH UT	1	3533.40	175.00	1
6	Head Lamp - RH call	1		1,859.40	1
7	Head Lamp Lower Bracket - RH and	. 1	2842.72	45.00	
8	Front Fender - RH	1		582.30	4.
9	Front Fender Air Protector - RH	1		193.00	
10	Front Fender Air Protector Clips - RH	1	a tol the lagar	20.00	
			\$	4,159.30	
	Less 20%		Secretary of the s	(831.86)	
			\$	3,327.44	
	S/NETT ITEMS				
1	Front Wheel Rim - RH He	1		850.00	X.
	Total parts		\$	4,177.44	
	LABOUR CHARGE				
1	To knocking out front & rear portion & renew above parts		\$	600.00	400
2	To putty & spray up paint works		\$	600.00 600.00 50.00	400
3	To check wiring system		\$	50.00	30
4	To underseal		\$	100.00	X

RE: ESTIMATE FOR ACCIDENT REPAIR SMK2655K (HONDA VEZEL)

Total Labour \$ 1,500.00

Grand Total \$ 5,677.44

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

total: 3672.72 (P/P)
04 Dayp.