

01 want to do  
private settlement.

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Tel : 6389 - 6111

Fax : 6224 - 7478 / 7175

**Quotation**  
 DATE : 19.10.2020  
 VEH NO : SMK2655K  
 MODEL : Honda Vezel  
 D O A : 01.10.2020  
 YR REF : SLS3993Y

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SMK2655K (HONDA VEZEL)**

| Item      | Description                                      | Qty   | Amt         |
|-----------|--------------------------------------------------|-------|-------------|
| <b>NO</b> | <b>LIST ITEMS</b>                                |       |             |
| 1         | Front Bumper <i>2 hand</i>                       | 1     | 880.00 ✓    |
| 2         | Front Bumper Clips <i>new</i>                    | 1 set | 30.00 ✓     |
| 3         | Front Bumper Side Holder - RH <i>new</i>         | 1     | 23.60 x     |
| 4         | Front Bumper Lower Garnish <i>cut</i>            | 1     | 351.00 ✓    |
| 5         | Front Bumper Fog Lamp Cover - RH <i>cut</i>      | 1     | 175.00 ✓    |
| 6         | Head Lamp - RH <i>cracked</i>                    | 1     | 1,859.40 ✓  |
| 7         | Head Lamp Lower Bracket - RH <i>cracked</i>      | 1     | 45.00 ✓     |
| 8         | Front Fender - RH <i>Repair</i>                  | 1     | 582.30 x    |
| 9         | Front Fender Air Protector - RH <i>cut</i>       | 1     | 193.00 ✓    |
| 10        | Front Fender Air Protector Clips - RH <i>new</i> | 1     | 20.00 ✓     |
|           |                                                  |       | \$ 4,159.30 |
| Less 20%  |                                                  |       | (831.86)    |
|           |                                                  |       | \$ 3,327.44 |

**S/NETT ITEMS**

|                    |                                  |   |                    |
|--------------------|----------------------------------|---|--------------------|
| 1                  | Front Wheel Rim - RH <i>stem</i> | 1 | 850.00 x           |
| <b>Total parts</b> |                                  |   | <b>\$ 4,177.44</b> |

**LABOUR CHARGE**

|   |                                                          |    |                   |
|---|----------------------------------------------------------|----|-------------------|
| 1 | To knocking out front & rear portion & renew above parts | \$ | 600.00 <i>400</i> |
| 2 | To putty & spray up paint works                          | \$ | 600.00 <i>400</i> |
| 3 | To check wiring system                                   | \$ | 50.00 <i>30</i>   |
| 4 | To underseal                                             | \$ | 100.00 x          |

**RE : ESTIMATE FOR ACCIDENT REPAIR SMK2655K (HONDA VEZEL)**

5 To perform wheel alignment

\$ 150.00

Total Labour

\$ 1,500.00

Grand Total

\$ 5,677.44

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3672.72 (P/P)

04 Days