

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SMP2661R

Type of Claim : TPVehicle No. : SMP2661RMake & Model : BLUECAR / BLUECARBLYear of Manufacture : 2019Chassis No. : VL4BCEB4RKT003669Ins Company : EQ INSURANCE COMPANY LIMITEDEngine No. : 922403C19W123600627Excess : -Policy No. : -Date of Accident : 22/09/2020Time of Accident : 17:00:00Suggested Days of Repair : 6Case Owner : BLUECAR EAST ASIA PTE LTDTP Vehicle No. : SBN6888T**Repair Estimates**Parts (a) Cost / List Price Items \$ 2,890.00Plus/Less— 20.0% \$ 578.00Total of Cost / List \$ 3,468.00(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,468.00Labour (Appendix B) \$ 2,050.00Total Repair Cost \$ 5,518.00**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s), during repair
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qianf 8288 0282Company : LKKSurvey conducted on : 06/10/2020 at **Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : Date:

part by part.

before paint photos.

After paint photos.

ESTIMATED REPAIR COST DETAILS

Vehicle No SMP2661R Case Owner BLUECAR EAST ASIA
PTE LTD
 Make & Model BLUECAR / BLUECARBLUECA Year Manufacture 2019
 Chassis No VL4BCEB4RKT003669 Engine No 922403C19W123600627
 Date & Time Supplier
 Order By Type of Claim TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT FENDER RH / B/C	1	\$ 1,008.00	\$ 1,008.00			
2	FRONT FENDER RH COVER / C/P	1	\$ 189.00	\$ 189.00			
3	TYRE ASSEMBLY FRONT RH / Sun	1	\$ 234.00	\$ 234.00			
4	TYRE PRESSURE SENSOR / ?	1	\$ 159.00	\$ 159.00			
5	RIM ASSEMBLY FRONT RH / BT	1	\$ 217.00	\$ 217.00			
6	FRONT RH RIM COVER X N/V	1	\$ 45.00	\$ 45.00			
7	FRONT RH FENDER INNER SHEILD ?	1	\$ 150.00	\$ 150.00			
8	FRONT RH FENDER INNER SHEILD CLIP / MC	2	\$ 1.00	\$ 2.00			
9	FENDER SIDE LAMP RH / D/S	1	\$ 103.00	\$ 103.00			
10	FRONT RIGHT ABSORBER WITH MOUNTING ?	1	\$ 148.00	\$ 148.00			
11	TIE ROD END ?	1	\$ 79.00	\$ 79.00			
12	ANTI ROLL BAR U BOLT CS ?	1	\$ 5.00	\$ 5.00			
13	ANTI ROLL BAR TIE ROD RH ?	1	\$ 22.00	\$ 22.00			
14	FRONT RIGHT LOWER ARM ?	1	\$ 130.00	\$ 130.00			
15	BRAKE DISK GUARD RH FOR 257X22 DISK ?	1	\$ 4.00	\$ 4.00			
16	FRONT RIGHT KNUCKLE ARM ?	1	\$ 389.00	\$ 389.00			
17				\$ -			
18				\$ -			
19				\$ -			
20				\$ -			
21				\$ -			
22				\$ -			
23				\$ -			
24				\$ -			
25				\$ -			
26				\$ -			
27				\$ -			
28				\$ -			
29				\$ -			
30				\$ -			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 2,883.00 \$ 2,890.00 \$ - \$ - \$ -



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. : SMP2661R Case Owner
Make & Model : / BLUECARBLUECAR / BLUECAR Year of Manufacture

**BLUECAR
EAST ASIA
PTE. LTD.**
2019

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.