

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SMP2661R

Type of Claim : TPVehicle No. : SMP2661RMake & Model : BLUECAR / BLUECARBLYear of Manufacture : 2019Chassis No. : VL4BCEB4RKT003669Ins Company : EQ INSURANCE COMPANY LIMITEDEngine No. : 922403C19W123600627Excess : -Policy No. : -Date of Accident : 22/09/2020Time of Accident : 17:00:00Suggested Days of Repair : 6Case Owner : BLUECAR EAST ASIA PTE LTD**Repair Estimates**TP Vehicle No. : SBN6888T

Parts (a) Cost / List Price Items	\$ 2,890.00	1684
15%		
Plus/Less— 20.0%	\$ 578.00	
Total of Cost / List	\$ 3,468.00	1936.6
(b) Nett Price Items	\$ -	
Less	\$ -	
Total of Nett Item	\$ -	
(c) Special Nett Items	\$ -	120
Total Parts Cost (Appendix A)	\$ 3,468.00	
Labour (Appendix B)	\$ 2,050.00	
Total Repair Cost	\$ 5,518.00	3036.6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during repair
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qianf 8288 0282

Company : LKK

Survey conducted on : 06/10/2020 at _____

Remarks By Surveyor : part by part.
before paint photos.
After paint photos.

(a) The repair of this vehicle is authorized / is not authorized until further notice. 2

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

ESTIMATED REPAIR COST DETAILS

Vehicle No SMP2661R Case Owner BLUECAR EAST ASIA
PTE LTD
 Make & Model BLUECAR / BLUECARBLUECA Year Manufacture 2019
 Chassis No VL4BCEB4RKT003669 Engine No 922403C19W123600627
 Date & Time Supplier
 Order By Type of Claim TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT FENDER RH / <i>B/C</i>	1	\$ 1,008.00	\$ 1,008.00			
2	FRONT FENDER RH COVER / <i>CPA</i>	1	\$ 189.00	\$ 189.00			
3	TYRE ASSEMBLY FRONT RH / <i>Run</i>	1	\$ 234.00	\$ 234.00			120
4	TYRE PRESSURE SENSOR / <i>✓</i> NEC	1	\$ 159.00	\$ 159.00			
5	RIM ASSEMBLY FRONT RH / <i>BT</i>	1	\$ 217.00	\$ 217.00			
6	FRONT RH RIM COVER <i>X NN</i>	1	\$ 45.00	\$ 45.00			
7	FRONT RH FENDER INNER SHEILD <i>X NN</i>	1	\$ 150.00	\$ 150.00			
8	FRONT RH FENDER INNER SHEILD CLIP / <i>AC</i>	2	\$ 1.00	\$ 2.00			
9	FENDER SIDE LAMP RH / <i>DIS</i>	1	\$ 103.00	\$ 103.00			
10	FRONT RIGHT ABSORBER WITH MOUNTING <i>X NN1</i>	1	\$ 148.00	\$ 148.00			
11	TIE ROD END <i>X NN</i>	1	\$ 79.00	\$ 79.00			
12	ANTI ROLL BAR U BOLT CS <i>X NN</i>	1	\$ 5.00	\$ 5.00			
13	ANTI ROLL BAR TIE ROD RH <i>X NN</i>	1	\$ 22.00	\$ 22.00			
14	FRONT RIGHT LOWER ARM <i>X NN</i>	1	\$ 130.00	\$ 130.00			
15	BRAKE DISK GUARD RH FOR 257X22 DISK <i>X NN</i>	1	\$ 4.00	\$ 4.00			
16	FRONT RIGHT KNUCKLE ARM <i>X NN</i>	1	\$ 389.00	\$ 389.00			
17				\$ -			
18				\$ -			
19				\$ -			
20				\$ -			
21				\$ -			
22				\$ -			
23				\$ -			
24				\$ -			
25				\$ -			
26				\$ -			
27				\$ -			
28				\$ -			
29				\$ -			
30				\$ -			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 2,883.00 \$ 2,890.00 \$ - \$ - \$ -



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. : SMP2661R Case Owner
Make & Model : / BLUECARBLUECAR / BLUECAR Year of Manufacture

**BLUECAR
EAST ASIA
PTE. LTD.**
2019

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.