

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

QBE Insurance (Singapore) Pte Ltd

Blk 60 , Anson Road # 11 - 01
 Maple Tree Anson
 Singapore 179914
 Tel : 6224 - 6633
 Fax : 6534 - 5356

Quotation

DATE : 07.10.2020
 VEH NO : GBJ2568P
 MODEL : Nissan NV350
 D O A : 06.10.2020
 YR REF : GBF3558H

Jia Le.

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBJ2568P (NISSAN NV350)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Replaced</i>	1	600.50 ✓
2	Rear Bumper Side Holder - LH & RH <i>New</i>	2	46.80 ✓
3	Rear Bumper Step Panel <i>Replaced</i>	1	206.50 ✓
4	Rear End Panel <i>Repair</i>	1	537.20 ✓
5	Tail Lamp - LH & RH <i>New</i>	2	525.00 ✓
6	Tailgate <i>Replaced</i>	1	1,742.00 ✓
7	Tailgate Lock <i>Damaged</i>	1	281.50 ✓
8	Tailgate Lock Cover <i>New</i>	1	51.20 ✓
9	Tailgate Weatherstripe <i>New</i>	1	154.90 ✓
10	Tailgate Inner Trim Board <i>New</i>	1	131.00 ✓
11	Tailgate Chrome Moulding <i>At</i>	1	487.80 ✓
12	Tailgate Glass <i>Shattered</i>	1	985.50 ✓
13	Tailgate Glass Moulding <i>New</i>	1	155.00 ✓
14	Nissan Logo	1	65.70 ✓
15	NV350 Emblem <i>New</i>	1	101.30 ✓
16	Urban Emblem	1	59.70 ✓
			\$ 6,131.60
			(1,839.48)
			4,292.12

4685.50
4216.95.

10%.
 Less 20%

S/NETT ITEMS

1	Rear Bumper Clips <i>New</i>	1 set	30.00 ✓
2	Reverse Sensor <i>Damaged</i>	1 set	280.00 <i>200</i>
3	Tailgate Inner Trim Board Clips <i>New</i>	1 set	30.00 ✓
4	Tailgate Glass Sealant <i>New</i>	1 set	60.00 ✓
5	Advertisement Stickers <i>New</i>	1 set	400.00 <i>300</i>
6	Video Camera <i>Damaged</i>	1	500.00 <i>400</i>
7	70km/h Sticker <i>New</i>	1	15.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GBJ2568P (NISSAN NV350)

8	8 pax Sticker <i>new</i>	1	15.00 ✓
9	Tailgate Glss Solar Film . <i>new</i>	<i>1220</i>	1,330.00
	<i>300</i> <i>200.</i>	Less 10%	(133.00)
			1,197.00
Total parts			\$ 5,489.12

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 <i>600.</i>
2	To putty & spray up paint works	\$	1,200.00 <i>650.</i>
3	To check wiring system	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>30.</i>
6	To transfer tailgate fittings	\$	150.00 <i>80</i>
7	To replace tailgate glass	\$	180.00 <i>120.</i>
8	To vacuum glass shards	\$	120.00 <i>80</i>
9	To replace Video camera	\$	100.00 <i>50.</i>
Total Labour			\$ 3,250.00
Grand Total			\$ 8,739.12

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7/26.85
CP/P).
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: