

LKK Auto Consultants hence notify

the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

ALG - (CIP) JH

Date: 06.10.2020

Time: 17:20:32

Page: 1

COMPANY: THIRD PARTY'S CLAIM (CAS)
CUSTOMER: Subsequent item(s) must be resurveyed and
ADDRESS: COASTAL INSURANCE COMPANY
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
Acknowledged by Repaire
Signature: 65508755
Date:

JOB NO : 305426684
REGN NO : SH 6451A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 22.10.2019
DATE/TIME IN : 06.10.2020 15:20
ACCIDENT DATE : 06.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	/ BR
0002	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00	/ DEF
0003	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1	98.80	20.00	79.04	/ CMT
0004	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00	/ MC
0005	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/ MC
0006	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70	/ BR
0007	04-01-0104-2288-G	IONIQVC BEAM-RR BUMPER	1	294.80	20.00	235.84	/ BR
0008	FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00	/ BR
						SUB-TOTAL : 1,271.70	/

JOB NATURE

0000	PB	PANEL BEATING	400.00	J2s
0001	SP	SPRAYPAINT CHARGE	300.00	900
0002	L	REMOVE/REFIX REVERSE SENSOR ASSY	80.00	30 550

Steve CLKKJ nrl nrl
2 chys
P/P
Ry ReL SH
7/10/20, 10.30am

P- 1271-70
L- 550
1821-70